

## HIGHWAY SAFETY RESEARCH CENTER CAR SEAT RECALL LIST ARCHIVE

Last Revision: September 23, 2019

**Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)**

### About Car Seats and Recalls

It is very important to pay attention to recall notices and for parents to check if their seats are safe to use. Recalls can be issued for any failure to meet Federal Motor Vehicle Safety Standard 213. Most recalls are issued due to reasons related to the crashworthiness of the car seat, but some recalls are for deviations from the standards related to labeling requirements, flammability of the upholstery or padding, or for parts that may come loose and pose a choking hazard. All recalls should be corrected.

Car seats are required to have a label indicating the manufacturer, model information, and date of manufacture. Car seats should not be used if these labels are missing. It is important for people to register their car seat by either mailing the registration card to the manufacturer or by contacting the manufacturer directly.

In cases where the manufacturer of a recalled seat has gone out of business or discontinued replacement programs, parents are advised to discontinue use of the seat. Discarded seats should be taken apart and stripped of upholstery, padding and straps and then destroyed by having them crushed to prevent others from using them.

To report any suspected car seat defects, call the National Highway Traffic Safety Administration Auto Safety Hotline at 888-327-4236 / (TTY): 800-424-9153.

### About Older Car Seats and Recalls

The older model list includes recalled seats that are now 10 or more years old. Caregivers will sometimes choose to use older car seats even though it not recommended. Knowing that a particular model is under recall should help to encourage the caregiver to destroy the older seat and obtain a new one.

### About the HSRC Recall List

The UNC Highway Safety Research Center (HSRC) car seat recall list is updated as soon as possible after recall notifications are announced and after the information can be verified for completeness and accuracy. Users of this (or any other) recall list should remind parents/caregivers to contact the manufacturer to be certain whether or not a particular car seat is affected by any recalls and how to proceed with repairs or replacement.

### Instructions for Using the HSRC Recall List

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the manufacturer, model, and dates of manufacture match any of the listings. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

For further information, contact:

Bevan Kirley or Kristel Robison

The University of North Carolina Highway Safety Research Center

800-672-4527 x2 or [cps@hsrc.unc.edu](mailto:cps@hsrc.unc.edu)

[www.buckleupnc.org/car-seat-recall-list](http://www.buckleupnc.org/car-seat-recall-list)

This Page Intentionally Left Blank

Car seats manufactured before 1981 were not required to be crash tested and must not be used. Most manufacturers stamp their car seats with an expiration date, typically six to eight years from the date of manufacture, on a label or in the shell of the seat. Many child passenger safety advocates recommend that if no expiration date can be found, car seats older than ten years should be replaced by a new one. Older models are included as a part of this recall list because care givers will sometimes choose to use older car seats even though it goes against the recommendations of most organizations and advocates. Knowing that a particular model is under recall, and if the defect cannot be corrected, should help to encourage the care giver to destroy the older seat and obtain a new one.

**Following are recalls and safety notifications that were issued for models where all or most models sold are at least 10 years old as of September 23, 2019.** The listing of older models with recalls will only be updated as "newer" models get to be old enough to be moved to the "older" models list.

Programs that make multiple copies of the HSRC recall list, e. g., for use at clinics or permanent checking/fitting stations, should only have to make copies of this older model section when it is revised, regardless of how often the main (newer model) section is revised. Most clinics or permanent checking/fitting stations should only need to print/copy one or two older model lists for reference. Updated versions of this list, as well as the list of models less than 10 years old, are posted on-line at [www.buckleupnc.org/car-seat-recall-list](http://www.buckleupnc.org/car-seat-recall-list).

## CAR SEATS 10 YEARS OLD AND OLDER

Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)

Refer to Page 23 for the Index of Recalls and Safety Notifications

<i>List No.</i>	<i>Manufacturer Model # ("X" = more numbers or letters follow)</i>	<i>Customer assistance Mfg Date</i>	<i>Problem Type and Consumer Action</i>
-----------------	--	-------------------------------------	---

### **Alcot (Childcare)**

**ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY & REPLACE**

201) Child Love Seat

3/84-11/84 Plastic shell may develop cracks. Destroy & replace seat.

### **All Our Kids**

**ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY & REPLACE**

202) Little Cargo Vest 600

4/93-3/94 Flammability of upholstery. Call mfg. for repair info.

203) Little Cargo Vest 602

3/94-9/94 Flammability of upholstery. Call mfg. for repair info.

### **Alpha Elite (Dorel)**

**Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141  
[www.djgusa.com](http://www.djgusa.com)**

204) Alpha Luxe 22462x

05/01/08-04/30/09 Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.

205) Alpha Omega All-N-1 Alpha Omega Elite 22459x 22148x, 22149x, 22158x

05/01/08-04/30/09 Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Alpha Elite (Dorel) (continued)**

- |      |                     |                         |                       |   |
|------|---------------------|-------------------------|-----------------------|---|
| 206) | Comfort Infant Seat | 22331 BLA,<br>22332 RLA | 07/26/05-<br>02/28/06 | Trim screws on handle can loosen resulting in a potential choking hazard. Contact mfg. at 877-229-1374 for free repair kit. Make sure the handle trim screws are tight and continue to use the existing seat while waiting to receive and install the repair kit. |
| 207) | Comfort Infant Seat | 22331 BLA,<br>22332 RLA | 07/26/05-<br>02/28/06 | Some consumers have experienced difficulty installing the base in certain vehicles. Dorel will replace the original version of the base at no charge to the customer. Contact mfg. at 877-229-1374 to determine eligibility for a replacement base.               |

**Alpha Sport (Dorel)****Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141  
www.djgusa.com**

- |      |         |                |                       |  |
|------|---------|----------------|-----------------------|--|
| 208) | Enspira | 22452x, 22458x | 05/01/08-<br>04/30/09 | Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit. |
| 209) | Vantage | 22546x, 22547x | 05/01/08-<br>04/30/09 | Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit. |

**American Motors****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM  
DISCONTINUED - DESTROY & REPLACE**

- |      |                  |     |            |   |
|------|------------------|-----|------------|---|
| 210) | Infant Love Seat | All | 1/81-12/82 | Plastic shell may develop cracks. Destroy & replace seat. |
| 211) | Child Love Seat  | All | 3/84-11/84 | Plastic shell may develop cracks. Destroy & replace seat. |

**Baby Trend****800-328-7363 - www.babytrend.com**

- |      |                      |                  |                       |   |
|------|----------------------|------------------|-----------------------|---|
| 212) | Rigid Latch-Loc      | 6439, 6448, 6481 | 05/14/07-<br>04/01/08 | Incorrect steel used on the latch connector can crack and allow the child seat base to detach from the vehicle's latch anchors during a severe crash. Contact mfg. for a replacement base. Install with vehicle seat belt until base is replaced. |
| 213) | Rigid Latch-Loc Base | 6400             | 05/14/07-<br>04/01/08 | Incorrect steel used on the latch connector can crack and allow the child seat base to detach from the vehicle's latch anchors during a severe crash. Contact mfg. for a replacement base. Install with vehicle seat belt until base is replaced. |

**Babyhood Industries****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM  
DISCONTINUED - DESTROY & REPLACE**

- |      |             |      |           |   |
|------|-------------|------|-----------|---|
| 214) | Wonda Chair | 810  | Pre 12/82 | Harness may be misrouted. Call mfg. for instructions. |
| 215) | Baby-Sitter | 8200 | 1/92-6/93 | Buckle. Call mfg. for repair info.                    |

**Basic Comfort****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM  
DISCONTINUED - DESTROY & REPLACE**

- |      |             |          |            |  |
|------|-------------|----------|------------|--|
| 216) | Galaxy 2000 | 960, 961 | ALL        | Crash test failure. Call mfg. for repair info.   |
| 217) | Galaxy 2000 | 960, 961 | 11/98-1/99 | Faulty molding of foam backs and cushions may allow separation of part of the booster seat. Call mfg. for repair info. |

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model # ("X" = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Customer assistance Problem Type and Consumer Action</b>
<b>Beatrix Potter (Dorel)</b>		<b>Dorel Juvenile Group: 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com</b>		
218)	Designer 22	02-621-SAL, 02-620-xxx	01/03/02- 02/13/02	Plastic handle can unexpectedly release from the carrying position when used as a carrier. Does not affect safety as a child restraint. Contact mfg. for repair kit.
<b>Bertini (Dorel)</b>		<b>Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com</b>		
219)	SureFit (Travel system)	22346x	05/01/08- 04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
<b>Bolform Corp.</b>		<b>ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY &amp; REPLACE</b>		
220)	Buckle-Up Harness	84E-019	ALL	Crash test failure. Destroy & replace.
<b>Britax</b>		<b>888-427-4829 / 704-409-1700 www.britaxusa.com</b>		
221)	Advantage	E902228	03/05/01- 07/26/01	One of the tether brackets of affected seats may separate from the tether attachment point. Contact mfg. for repair kit.
222)	Boulevard	E9L57	03/01/06- 08/01/06	Top tether hook can open during a crash allowing the restraint to change from an upright to a reclined position. Owners are being advised to discontinue use of the top tether when the child reaches 50 lbs. Contact mfg. for replacement labels.
223)	Companion	E9L14	10/31/03- 06/06/04	One or both of two tabs on the bottom of the carrier may not be properly seated and may allow the carrier to rotate in the base too far in a crash. Correct/incorrect assembly can be determined by visual examination. Call mfg. for replacement info. Affected units may be installed without the base until receiving a replacement.
224)	Companion	E9L14, E9L20, E9L80	Pre- 11/01/07	User Guide Update - NOT A RECALL: Britax has updated instructions regarding adjustment of the buckle strap position and maximum height for infant carrier use. The inner buckle strap position should be used for infants weighing less than 11 pounds. A child has exceeded the height limit for the Companion when the top of the head is less than one inch from the top of the child restraint or the child's height exceeds 30 inches (76 cm). Contact mfg for updated user guide and labels
225)	Decathlon	E9L47	02/12/05- 07/31/07	Under certain circumstances the harness adjuster housing may separate from the child restraint shell and allow the adjuster to move out of position. If this happens caregivers may experience difficulty adjusting the harness. Call mfg. for repair info.
226)	Freeway	101	6/96-4/97	Buckle. Call mfg. for repair info.
227)	Frontier	E9L54E7, E9L54H6, E9L54H7, E9L54M6	04/01/08- 09/14/08	Harness straps may become detached from the metal yoke on the back of the seat If they are loosened one strap at a time with excessive force. Contact mfg. for repair kit.
228)	Frontier	E9L5490	04/01/08- 09/17/08	Harness straps may become detached from the metal yoke on the back of the seat If they are loosened one strap at a time with excessive force. Contact mfg. for repair kit.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Britax (continued)**

229)	Husky	E9L30	08/01/02-12/31/03	Head excursions higher than allowed by FMVSS 213 could result when installed as instructed with a long/serpentine belt path. Contact mfg. for replacement labels advising the use of an alternative short belt path.
230)	Husky	E9L30	Pre-07/24/04	The adjuster strap may slip within the metal buckle that controls the tightness of the shoulder harness and may allow the harness to loosen. Contact mfg. for repair kit.
231)	Marathon	E9L06	Pre-07/24/04	The adjuster strap may slip within the metal buckle that controls the tightness of the shoulder harness and may allow the harness to loosen. Contact mfg. for repair kit.
232)	Marathon	E9L06, E9W06, E906 with top tether lot # KGR 01 A	05/23/06-07/28/06	The top tether hook may open and have the potential to release from the tether anchor if the child exceeds 50 pounds. Contact mfg. for repair kit.
233)	Regent	E9L39x	11/10/05-06/18/07	Consumer Advisory/Product Update - NOT A RECALL: Britax has modified the Regent and revised the installation instructions. Contact mfg. to receive a free product update kit that includes a revised user guide, replacement belt-routing label, a longer LATCH connector strap, and adhesive slip resistant strips.
234)	Regent Classic	E9L3998	12/18/06-01/18/07	Affected seats were produced with an incorrect airbag warning label attached to the cover. Contact mfg. to receive a free replacement cover.
235)	Roundabout	161	1/99-3/99	Possible faulty molding of shell can allow excessive head excursion. Call mfg. for repair info.
236)	Super Elite	E9031	04/25/01-02/15/02	Harness may allow too much forward head movement. Contact mfg. to receive a free replacement harness system.
237)	Super Elite	E9031	04/01/01-08/31/02	Harness adjuster tab may begin to stick after prolonged use. Harness may loosen if it sticks in the open position. Contact mfg. for repair kit and installation instructions.
238)	Traveller Plus	E9L32 (Mfg. by Britax for Snug Seat)	Pre-07/24/04	The adjuster strap may slip within the metal buckle that controls the tightness of the shoulder harness and may allow the harness to loosen. Contact mfg. for repair kit.
239)	Wizard	E9L07	Pre-07/24/04	The adjuster strap may slip within the metal buckle that controls the tightness of the shoulder harness and may allow the harness to loosen. Contact mfg. for repair kit.

**Century Products****800-837-4044 / 216-468-2000**

240)	100	4100	1/81-4/81	Upholstery buttons. Call mfg. for repair info.
241)	100	4100	4/85-2/86	Plastic shell may crack in crash. Call mfg. for repair info.
242)	1000 STE	4153, 4163, 4180	12/90-10/91	Incorrect labels on seat. Call mfg. for corrections
243)	200	4200, 4210, 4235, 4214, 4223	1/81-4/81	Upholstery buttons. Call mfg. for repair info.
244)	200	4200, 4210, 4235, 4214, 4223	June 81	Washers on frame. Call mfg. for repair info.
245)	200	4200, 4210, 4235, 4214, 4223	1/81-1/83	Buckle. Call mfg. for repair info.
246)	200	4200, 4210, 4235, 4214, 4223	4/85-2/86	Plastic shell may crack in crash. Call mfg. for repair info.
247)	2000 STE	4253, 4263, 4265	4/84-6/89	Harness. Call mfg. for repair info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Century Products (continued)**

248)	2000 STE	4253, 4261, 4263, 4265, 4266	12/90-10/91	Incorrect labels on seat. Call mfg. for corrections
249)	2000 STE	4253, 4261, 4263, 4265, 4266	12/91-4/92	Buckle. Call mfg. for repair info.
250)	300	4300, 4302, 4303, 4323, 4310, 4334, 4335	4/85-2/86	Plastic shell may crack in crash. Call mfg. for repair info.
251)	3000 STE	4365DT, 4366	3/89-10/89	Upholstery. Call mfg. for repair info.
252)	3000 STE	4353, 4365, 4366, 4368	5/90-6/90	Crash test failure of buckle. Call mfg. for repair info.
253)	3000 STE	4353, 4365, 4366, 4368	Pre 91	Buckle instructions. Call mfg. for corrections
254)	3000 STE	4365, 4366, 4367, 4368, 4369, 4380, 4381	12/90-10/91	Incorrect labels on seat. Call mfg. for corrections
255)	3000 STE	4353, 4365, 4366, 4367, 4368, 4369	10/89-4/92	Buckle. Call mfg. for repair info.
256)	3500 STE	4380	12/90-4/92	Buckle. Call mfg. for repair info.
257)	4-In-1 Travel System	11-570, 11-597, 11-600, 11-650	9/95-5/96	Buckle. Call mfg. for repair info.
258)	4-In-1 Travel System	11-564, 11-565, 11-570, 11-575, 11-576, 11-578, 11-595, 11-597, 11-598, 11-599, 11-600	01/01/91-07/31/97	Handle can break when the seat is used as an infant carrier causing the infant to fall to the ground be injured. Does not affect safety as car seat. Call 800-865-1419 for replacement handle.
259)	400XL	4400, 4434, 4436, 4446	4/85-2/86	Plastic shell may crack in crash. Call mfg. for repair info.
260)	400XL	4400, 4434, 4436, 4446	11/84-4/86	Shield. Call mfg. for repair info.
261)	5000 STE	4450, 4460, 4475	12/88-11/89	Buckle. Call mfg. for repair info.
262)	5000 STE	4450, 4460, 4470, 4475	5/90-6/90	Crash test failure of buckle. Call mfg. for repair info.
263)	5000 STE	4460, 4470, 4475, 4476, 4480, 4490	12/90-10/91	Incorrect labels on seat. Call mfg. for corrections
264)	5000 STE	4450, 4460, 4470, 4475, 4476	09/89-4/92	Buckle. Call mfg. for repair info.
265)	5000 STE	4450, 4460, 4470, 4475,	Pre 91	Buckle instructions. Call mfg. for corrections.
266)	5500 STE	4480, 4490	01/91-4/92	Buckle. Call mfg. for repair info.
267)	580	4581, 4583, 4585	6/86-10/89	Screws for carry handle. Call mfg. for repair info.
268)	580	4580, 4581, 4583, 4585	7/86-12/89	Incorrect instructions. Call mfg. for corrections.
269)	Accel	45100, 45200, 45600, 45700	04/09/01-05/10/01	Harness adjustment lock may allow webbing to slip during a serious crash when used in the forward facing mode for some models and lot codes. Call Century at 1-800-575-6097 for replacement info.
270)	Affinity Infant Seat	4575	9/95-5/96	Buckle. Call mfg. for repair info.
271)	Bravo	44622, 44630, 44631, 44662	04/09/01-05/10/01	Harness adjustment lock may allow webbing to slip during a serious crash when used in the forward facing mode for some models and lot codes. Call Century at 1-800-575-6097 for replacement info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model # ("X" = more numbers or letters follow)	Customer assistance Mfg Date	Problem Type and Consumer Action
----------	---	------------------------------	----------------------------------

**Century Products (continued)**

272)	Breverra Contour	4875	2/95-7/98	Product improvement campaign: Buckle for the harness can crack or break. Call mfg. for replacement information.
273)	Breverra Premiere	4885	2/95-7/98	Product improvement campaign: Buckle for the harness can crack or break. Call mfg. for replacement information.
274)	Child Love Seat	4600	3/84-11/84	Plastic shell may develop cracks. Destroy & replace seat.
275)	Encore	44612, 4662	04/09/01-05/10/01	Harness adjustment lock may allow webbing to slip during a serious crash when used in the forward facing mode for some models and lot codes. Call Century at 1-800-575-6097 for replacement info.
276)	Infant Car Seat	4535, 4560, 4565, 4590	9/95-5/96	Buckle. Call mfg. for repair info.
277)	Infant Car Seat	12-565, 4513, 4515, 4516, 4518, 4551, 4557, 4558, 4559, 4564, 4565, 4566, 4568, 4569, 4575, 4576, 4589, 4591, 4593, 4594, 4595, 4597	01/01/91-07/31/97	Handle can break when the seat is used as an infant carrier causing the infant to fall to the ground be injured. Does not affect safety as car seat. Call 800-865-1419 for replacement handle.
278)	Infant Love seat	4500, 4510, 4520	1/81-12/82	Plastic shell may develop cracks. Destroy & replace seat.
279)	Smart Fit	4525	9/95-5/96	Buckle. Call mfg. for repair info.
280)	Smart Move	4750	11/95-2/96	Buckle. Call mfg. for repair info.
281)	Smart Move	44709	04/09/01-05/10/01	Harness adjustment lock may allow webbing to slip during a serious crash when used in the forward facing mode for some models and lot codes. Call Century at 1-800-575-6097 for replacement info.

**Chicco****800-807-8817 / 877-424-4226 - www.chiccousa.com**

282)	Key Fit Key Fit 30 Cortina Travel Systems BASES ONLY	All	02/26/08-03/17/08	Recall applies only to bases manufactured between 2/26/2008 and 3/17/2008. When installed with LATCH, the webbing used to tighten the base can slip through the adjustment lock. Bases with serial number is between 08 02 26 (February 26, 2008) and 08 03 17 (March 17, 2008) are covered by this recall. Contact mfg. for replacement base. Install the base with the vehicle seat belts until replacement base is obtained.
------	--	-----	-------------------	---

**Chrysler****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY & REPLACE**

283)	Child Love Seat	All	3/84-11/84	Plastic shell may develop cracks. Destroy & replace seat.
------	-----------------	-----	------------	---

**Collier-Keyworth****800-544-1108**

284)	Co-Pilot	All	82-83	Shield. Call mfg. for repair info.
285)	Safe & Sound II	All	12/84-4/85	Buckle. Call mfg. for repair info.
286)	Commuter	All	10/87-02/88	Padding. Call mfg. for repair info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**



For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model # ("X" = more numbers or letters follow)</b>	<b>Customer assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Combi USA</b>		<b>800-992-6624 / 803-548-6633 - www.combi-intl.com</b>		
287)	Avatar	8100	11/12/03-05/07/04	Lower latch anchorage does not meet dynamic test requirements of FMVSS 213. Contact mfg. for free in-home repair kit and instructions. Affected models should be installed with the vehicle seat belt. Do not use the seat with the latch until repairs are made.
288)	Centre ST	8065	10/19/05-	The car seat could potentially become separated from its base in a crash. Mfg. recommends that the car seat be used without the base until it has been fixed. Contact mfg for free retrofit kit. Also affected are travel systems (# 4400, 4515, and 4520) that contain the Centre and Shuttle car seats.
	Centre DX	8074	12/15/07	
	Centre EX	8086		
	Centre ARB	8520		
289)	Shuttle	8087	10/19/05-12/15/07	The car seat could potentially become separated from its base in a crash. Mfg. recommends that the car seat be used without the base until it has been fixed. Contact mfg for free retrofit kit. Also affected are travel systems (# 4400, 4515, and 4520) that contain the Centre and Shuttle car seats.
290)	Zeus Turn	8815	07/15/07 - 03/25/09	Harness webbing fails to meet FMVSS 213 minimum breaking strength requirements. Contact mfg. for free harness replacement kit and instructions. The seats can continue to be used until the kits are made available and repairs are made.
<b>Compass Baby</b>		<b>888-899-2229 - www.compassbaby.com</b>		
291)	Infant Car Seat	I420 ARD I420 FUO I420 MAR	05/07/06, 05/13/06, and 05/15/06	The metal slide crotch anchor can become dislodged allowing excessive movement of the child and cracking of the plastic shell. This problem was discovered during testing by the manufacturer. There have been no reports of injuries and no calls from consumers regarding problems. Contact mfg. for free repair kit.
<b>Cosco (Dorel)</b>		<b>Dorel Juvenile Group: 800-219-0509 / 866-611-3022 / 812-372-0141</b>		
292)	Alpha Omega	02-331, 02-332, 02-531, 02-533, 02-537, 02-555.	11/17/00-01/10/01	Tether webbing could be cut and separate in a crash allowing excessive movement of the child. Contact mfg. for free repair kit.
293)	Alpha Omega	02332, 02531, 02533, 02537, 02555	01/01/00-09/30/01	Tether webbing does not conform to abrasion requirements of FMVSS 213. Contact mfg. for free repair kit.
294)	Alpha Omega	22150, 22180, 22269	11/01/03-	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
	Alpha Omega Elite	22155	12/31/05	
295)	Alpha Omega Elite	22154x, 22155x, 22158x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
296)	Alpha Omega All-N-1	22150x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
297)	Arriva	02-751	03/95-05/95	Buckle. Call mfg. for repair info.
298)	Arriva	02-729 TED	03/31/99-04/07/99	Airbag warning label is missing on seat pad. Fabric color noted by "TED" is only one affected. Call mfg. for replacement pad.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Cosco (Dorel) (continued)**

299)	Arriva	02-665, 02-727, 02-728, 02-729, 02-731, 02-732, 02-733, 02-750, 02-751, 02-755, 02-756, 02-757, 02-774	03/01/95- 01/31/00	Handle locks can unexpectedly release when used as a carrier, causing the seat to flip forward. Does not affect safety as car seat. Call mfg. for repair info. [Note: a recall campaign initiated 06/25/03 added models made through 01/31/00 to a previous recall of those made through 09/97.]
300)	Infant Car Seat	22-300 CSF, 22-300 FZN, 22-300 JJV, 22-300 OSF, 22-300 THD, 22-300 TWD	01/06/08-0 4/06/09	The child restraint carry handle can loosen and come off posing a fall hazard to infants. The safety as a child restraint is not affected. Do not use handle until repaired. Contact mfg. for free repair kit. NOTE: Only those models sold as a part of the Spirit and Sprint Travel Systems are affected.
301)	Commuter	02-086	11/87-2/88	Upholstery/padding. Call mfg. for repair info.
302)	Designer 22	22-300-JOS GB1B	08/19/03- 10/20/04	Harness can loosen if not properly tightened. Contact mfg. for free repair kit. Parents should continue to use the seat while waiting to receive/install the repair kit but are advised to make sure that the seat is properly adjusted while in use. NOTE: Models involved were sold only as travel systems (with a stroller) and any line code other than GB1B in the model # is not included in the recall.
303)	Dream Ride	02-719 ARQ	01/89- 01/94	Upholstery flammability. Call mfg. for repair info.
304)	DreamRide	22-001FSM	12/01/03- 04/28/04	Failed to meet back support angle requirements of FMVSS 213. Discontinue rear-facing use and use only as a car bed or request free replacement rear-facing child restraint from DJG. Contact mfg. for warning label and information.
305)	Hi Back Booster	02409, 02442, 02443, 02445, 02448, 02449, 02450, 02480, 02495	01/01/00- 09/30/01	Tether webbing does not conform to abrasion requirements of FMVSS 213. Contact mfg. for free repair kit.
306)	Hi Back Booster	02442, 02443, 02448, 93443, 93514	03/15/02- 08/01/02	UV stabilizer in harness webbing does not conform to requirements of FMVSS 213. Contact mfg. for free repair kit.
307)	High Rise Booster	22-297, 22-298, 22-299	10/01/03- 10/31/03	Incorrect warning label stating it is for use forward facing for children under one year of age rather than OVER one year of age. Contact mfg. for free replacement label and instructions.
308)	Luxury Soft Shield Auto Trac	02-790, 02-890	10/89-6/90	Crash test failure. Call mfg. for repair info.
309)	Regal Ride	22139MON	09/28/04-0 9/20/07	Elastic straps on padding can come loose and become accessible to the child allowing the child to loop the elastic strap around portions of his/her body. Contact mfg. for repair kit.
310)	Safe-T-Shield	81A or B, 181A or B	10/80-6/83	Shield. Call mfg. to replace seat.
311)	Safe-T-Mate		1984	Wrong instructions. Call mfg. for repair info.
312)	Safe and Easy	313	1/84-6/85	Plastic shell. Call mfg. for repair info.
313)	Safe and Snug	323, 423	1/84-6/85	Plastic shell. Call mfg. for repair info.
314)	Sidekick Booster	244x	04/96-5/97	Crash test failure of shield. Use only as belt-positioning booster. Call mfg. for refund info.
315)	Soft Shield	02-090	10/89-6/90	Crash test failure. Call mfg. for repair info.
316)	Soft Shield Auto Trac	02-290	10/89-6/90	Crash test failure. Call mfg. for repair info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model # ("X" = more numbers or letters follow)</b>	<b>Customer assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Cosco (Dorel) (continued)</b>			
317)	Soft Shield Deluxe 02-190	10/89-6/90	Crash test failure. Call mfg. for repair info.
318)	Touriva 02-084	5/94-8/94	Buckle. Call mfg. for repair info.
319)	Touriva Shield 02-014-EMF, 02-014-GDM, 02-015-PDL	8/97 (Mold #3)	Crash test failure of shell in front-facing recline position. Call mfg. for repair info.
320)	Touriva 5-point 02-514-BWE, 02-584-OXF, 02-518-NDF	8/97 (Mold #3)	Crash test failure of shell in front-facing recline position. Call mfg. for repair info.
321)	Touriva T-Shield 02-084, 02-094, 02-096, 02-404, 02-821	5/96-11/97	Crash test failure of post-test release pressure standard for the buckle. Call mfg. for repair info.
322)	Touriva 02014, 02015, 02019, 02084, 02094, 02114, 02504, 02514, 02518, 02519, 02524, 02584, 02803, 02806, 02821, 02825, 02935, 93084, 93094, 93514	01/01/00- 09/30/01	Tether webbing does not conform to abrasion requirements of FMVSS 213. Contact mfg. for free repair kit.
323)	Touriva 02514, 02519, 02524, 22100, 93446, 93504	03/15/02- 08/01/02	UV stabilizer in harness webbing does not conform to requirements of FMVSS 213. Contact mfg. for free repair kit.
324)	Touriva 22100x, 22111x, 22130x, 93100x, 93111x	09/28/04-0 9/20/07	Elastic straps on padding can come loose and become accessible to the child allowing the child to loop the elastic strap around portions of his/her body. Contact mfg. for repair kit.
325)	Trooper 219x, 224x, 225x, 229x	10/96-2/97	Crash test failure. Call mfg. for repair info.
326)	Turnabout 02-667, 02-753, 02-756, 02-758, 02-759, 02-760, 02-761, 02-762, 02-763, 02-764, 02-765, 02-770, 02-771, 02-772	03/01/95- 01/31/00	Handle locks can unexpectedly release when used as a carrier, causing the seat to flip forward. Does not affect safety as car seat. Call mfg. for repair info. [Note: a recall campaign initiated 06/25/03 added models made through 01/31/00 to a previous recall of those made through 09/97.]
327)	Voyager Infant Seat/Stroller All	9/97-10/97	Potential dislodgement from stroller. Does not affect safety as car seat. Call mfg. for repair info.

**Disney (Dorel)****Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141  
www.djgusa.com**

328)	Infant Car Seat 22-305 NAB, 22-305 PPH, 22-355 LBF, 22-355 PWK, 22-627 AWF	01/06/08-0 4/06/09	The child restraint carry handle can loosen and come off posing a fall hazard to infants. The safety as a child restraint is not affected. Do not use handle until repaired. Contact mfg. for free repair kit. NOTE: Only those models sold as a part of the Propack Travel System are affected.
------	---	-----------------------	--

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model # ("X" = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Customer assistance Problem Type and Consumer Action</b>
<b>Downunder</b>		<b>ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY &amp; REPLACE</b>		
329)	Kangaroo Booster Seat	All (Pre- 1/98)		Safety improvement campaign: The shoulder belts may not be properly located when the child is placed in the restraint. The shoulder belt guides may not help achieve correct seat belt placement. Do not use this booster if the shoulder belt does not touch the child's chest.
<b>Eddie Bauer (Dorel)</b>		<b>Dorel Juvenile Group: 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com</b>		
330)	3-in-1	02-331, 02-332, 02-531, 02-533, 02-537, 02-555	11/17/00-01/10/01	Tether webbing could be cut and separate in a crash allowing excessive movement of the child. Contact mfg. for free repair kit.
331)	3-in-1 Deluxe 3-in-1 Deluxe Convrt.	22740, 22750, 22755, 22756, 22757, 22770	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
332)	Alpha Omega Alpha Omega Elite	22750, 22755, 22756, 22757, 22770	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
333)	Comfort Infant Seat	22630xxx, 22631xxx	07/26/05-02/28/06	Trim screws on handle can loosen resulting in a potential choking hazard. Contact mfg. at 877-229-1374 for free repair kit. Make sure the handle trim screws are tight and continue to use the existing seat while waiting to receive and install the repair kit. (The 22630 models are part of the 01726 Eddie Bauer Integrated Travel System.)
334)	Comfort Infant Seat	22630xxx, 22631xxx	07/26/05-02/28/06	Some consumers have experienced difficulty installing the base in certain vehicles. Dorel will replace the original version of the base at no charge to the customer. Contact mfg. at 877-229-1374 to determine eligibility for a replacement base.
335)	Deluxe 3-in-1	22755x, 22758x, 22759x, 22790x, 22799x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
336)	Designer 22	22-625 xxx GB1B	08/19/03-10/20/04	Harness can loosen if not properly tightened. Contact mfg. for free repair kit. Parents should continue to use the seat while waiting to receive/install the repair kit but are advised to make sure that the seat is properly adjusted while in use. NOTE: Models involved were sold only as travel systems (with a stroller) and any line code other than GB1B in the model # is not included in the recall.
337)	Enspira	22740	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
338)	Enspira	22740x, 22741x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
339)	Hi Back Booster	02409, 02442, 02443, 02445, 02448, 02449, 02450, 02480, 02495	01/01/00-09/30/01	Tether webbing does not conform to abrasion requirements of FMVSS 213. Contact mfg. for free repair kit.
340)	Infant Car Seat	22-627 CGT, 22-627 FRK, 22-627 KGS, 22-627 SNW, 22-627 WPR, 22-655 BYTE	01/06/08-04/06/09	The child restraint carry handle can loosen and come off posing a fall hazard to infants. The safety as a child restraint is not affected. Do not use handle until repaired. Contact mfg. for free repair kit. NOTE: Only those models sold as a part of the Adventurer and Endeavor Travel Systems are affected.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model # ("X" = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Customer assistance Problem Type and Consumer Action</b>
<b>Eddie Bauer (continued)</b>				
341)	Prospect Adjustable Hiback Booster	22880x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
342)	SureFit	22657x, IC072x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
343)	Touriva	02870, 02871, 02875	01/01/00-09/30/01	Tether webbing does not conform to abrasion requirements of FMVSS 213. Contact mfg. for free repair kit.
<hr/>				
<b>Eventflo</b>			<b>800-525-2472 / 800-233-5921</b>	
344)	410	410	6/88-4/89	Harness/shield. Call mfg. for repair info.
345)	Bobby Mac Champion	411	4/85-4/90	Buckle. Call mfg. for repair info.
346)	Bobby Mac Deluxe	412, 414, 415, 416	4/85-4/90	Buckle. Call mfg. for repair info.
347)	Booster Seat	470, 471	2/87-8/88	Upholstery buttons. Call mfg. for repair info.
348)	Booster Seat	242, 470, 471	4/85-4/90	Buckle. Call mfg. for repair info.
349)	Champion	224x	06/93-11/96	Crash test failure. Call mfg. for repair info.
350)	Champion	224x	06/93-11/96	Crash test failure. Call mfg. for repair info.
351)	Champion	219x, 224x, 225x, 229x	10/96-2/97	Crash test failure. Call mfg. for repair info.
352)	Cozy Carry	272x, 273x, 468x, 469x, 476x, 477x, 478x, 480x, 481x	ALL (11/01/01-08/31/02)	Upgrade Kit - Not a Recall: For owners of Cozy Carry infant car seats to improve the performance of the detachable base in certain types of collisions. The kit is only for detachable bases with the words "Cozy Carry" on them. Visit <a href="http://www.cozycarry.com">www.cozycarry.com</a> or call 800-582-6698 for free kit.
353)	Discovery	390, 391, 534, 552	Pre-02/01/08	Voluntary Safety Recall - Testing showed that the car seat could potentially become separated from its base in high impact side collisions. Contact mfg. for free supplemental dual-hook fastener for enhanced safety performance.
354)	Discovery	3021769Z, 3021854Z	02/04/08	A small number of Discovery car seats may have shipped without complete assembly of the red release handle located on the back of the seat making it possible for the seat to separate from its base. Contact mfg. for replacement seat and base. Affected models can be used without the base while waiting for replacement.
355)	Dyn-O-Mite	441 thru 448	1/85-1/89	Crash test failure. Call mfg. for repair info.
356)	Dyn-O-Mite	202, 441 thru 448	4/85-4/90	Buckle. Call mfg. for repair info.
357)	Embrace	Begins with 317, 320, 397, 398, 540, 548, 549, 550, 556, 597, 598, 599	Pre-04/08/06	When used as an infant carrier, the handle can unexpectedly release, causing the seat to rotate forward. Handle should not be used until the repair kit has been installed. Affected restraints can continue to be used as a car seat properly installed in a vehicle. Contact mfg. for a free repair kit.
358)	First Choice	3604098	01/16/09-09/29/09	A label containing certain contact and certification information was inadvertently left off these car seats. Contact mfg. for a set of replacement labels.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Evenflo (continued)**

359)	Infant Car Seat	456, 458	Pre 4/89	Crash test failure. Call mfg. for repair info.
360)	Infant Car Seat	201, 202, 441 thru 446, 448, 456, 458	4/85-4/90	Buckle. Call mfg. for repair info.
361)	Joyride	Begins with 203, 205, 210, 435, 493	01/88-12/98	When used as an infant carrier, the carry handle can unexpectedly release, cause the seat to flip forward, and cause infant to fall to the ground. Call mfg. for repair info.
362)	On My Way	Begins with 206	05/94-05/95	Crash test failure. Call mfg. for repair info.
363)	On My Way	Begins with 207, 492	12/95-07/97	When used as a carrier, the locking mechanism on the handle can slip, flipping the seat forward and tossing the baby on the ground. Call mfg. for repair info.
364)	On My Way	Begins with 200, 211, 447, 499	Pre-02/10/00	Safety Notification: Alignment posts in base can become bent after repeated use. Contact mfg. for free upgrade kit.
365)	On My Way base	639001, 639002	Pre-02/10/00	Safety Notification: Alignment posts in base can become bent after repeated use. Contact mfg. for free upgrade kit.
366)	One-Step	221, 401 thru 409	04/85-04/90	Buckle. Call mfg. for repair info.
367)	One-Step Deluxe	222, 223, 4176	04/85-04/90	Buckle. Call mfg. for repair info.
368)	Scout	229x	06/93-12/96	Crash test failure. Call mfg. for repair info.
369)	Scout	219x, 224x, 225x, 229x	10/96-02/97	Crash test failure. Call mfg. for repair info.
370)	Seven Year Seat	453, 454	02/87-08/88	Upholstery buttons. Call mfg. for repair info.
371)	Seven Year Seat	228, 453, 454	04/85-04/90	Buckle. Call mfg. for repair info.
372)	Travel Tandem (Joyride + base)	205x	01/88-03/96	Test failure with base. Use without base and call mfg. for repair info.
373)	Travel Tandem (Joyride + base)	205x, 210x	01/88-12/98	When used as an infant carrier, the carry handle can unexpectedly release, cause the seat to flip forward, and cause infant to fall to the ground. Call mfg. for repair info.
374)	Tribute	378x, 379x	09/08/05-09/22/05	Certain areas of the plastic shell may be prone to stress fractures. Call mfg. to receive a replacement seat.
375)	Triumph	264x	10/20/01-01/31/02	Slide loop connectors in the harness may not be strong enough to fully secure the child in a crash. Call mfg. for repair kit.
376)	Triumph	264x, 359x, 389x	09/06/01-10/31/05	Portions of the cloth cover can be pulled back exposing the foam liner in an area that is reachable by a child occupant. A child inside the seat may break off and potentially choke on a piece of the foam liner. Contact mfg. for repair kit.
377)	Trooper (shield)	21940, 219164, 219180, 219186, 219188	11/95-1/96	Instructions. Call mfg. for new instructions
378)	Two-in-One	636x, 637x	1/98-3/98	In crash tests, the seat's backrest and base have separated when 5-point harness was being used. Call mfg. for information and replacement seat.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Evenflo (continued)**

379)	Ultara 1	420	9/88-7/89	Buckle. Call mfg. for repair info.
380)	Ultara 1	231	2/93-8/93	Plastic sleeve on harness. Call mfg. for repair info.
381)	Ultara II	227	1/90-6/90	Crash test failure. Call mfg. for repair info.
382)	Ultara II	232	2/93-8/93	Plastic sleeve on harness. Call mfg. for repair info.

**Fisher Price****ALL MODELS OLDER THAN 10 YEARS - DESTROY & REPLACE**

383)	Car Seat	9100	Pre-1987	Harness/shield. Call mfg. for repair info.
384)	Car Seat	9100, 9101	4/85-1/89	Upholstery. Call mfg. for repair info.
385)	Car Seat	9100, 9101	2/90-3/90	Buckle. Call mfg. for repair info.
386)	Car Seat	9100	4/85-8/85	Shield. Call mfg. for repair info.
387)	Car Seat	9100, 9101	5/87-1/89	Buckle. Call mfg. for repair info.
388)	Car Seat	9100, 9101	2/89-11/89	Buckle (extended 5/87-1/89). Call mfg. for repair info.
389)	Car Seat	9100, 9101	Pre 91	Loose button. Call mfg. for repair info.
390)	Car Seat	9100, 9101	2/91-1/92	Harness/shield. Call mfg. for repair info.
391)	Car Seat	9100, 9101	Pre 7/89	Label on shield. Call mfg. for repair info.
392)	Delux Car Seat	9104	6/15-9/92	Buckle. Call mfg. for repair info.
393)	Infant Seat	9149	1/91-2/91	Shield. Call mfg. for repair info.
394)	Infant Seat	9173	9/94-10-94	Air bag label. Call mfg. for repair info.
395)	Booster	9104	4/92-9/92	Buckle. Call mfg. for repair info.
396)	Booster	9104	4/92-9/92	Buckle. Call mfg. for repair info.
397)	Safe Embrace	79700	5/97-3/98	Harness adjuster. Call mfg. for repair info.

**Ford****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY & REPLACE**

398)	Infant Love Seat	All	81/82	Plastic shell may develop cracks. Destroy & replace seat.
------	------------------	-----	-------	---

**General Motors****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY & REPLACE**

399)	Infant Love Seat	All	81/82	Plastic shell may develop cracks. Destroy & replace seat.
400)	Child Love Seat	All	3/84-11/84	Plastic shell may develop cracks. Destroy & replace seat.

**Gerry****Contact Evenflo: 800-525-2472 / 800-233-5921**

401)	Guardian	All	01/90-05/90	Buckle. Call mfg. for repair info.
402)	Secure Ride	626	08/94-03-95	Air bag label. Call mfg. for new label

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model # ("X" = more numbers or letters follow)</b>	<b>Customer assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Graco</b>			
<b>800-345-4109 / www.gracobaby.com</b>			
403)	ComfortSport 8629x, 8630x, 8631x, 8632x, 8635x, 8639x, 8C00x, 8C01x, 8C02x, 8C03x, 8C04x, 8433x	01/02/07-07/31/07	Lower Anchorage belt may have been misrouted during assembly process. Use the vehicle seatbelt instead of LATCH to install affected models in the rear-facing position until it is inspected and, if necessary, corrected. Call mfg. or visit gracobaby.com website for additional info.
404)	ComfortSport 8C02MRC2	10/22/07	Seats were produced with foam thicker than specified and tested 1" thick foam. It is unclear as to what impact thicker foam will have on child seat safety. Call mfg. for seat replacement information.
405)	ComfortSport 8C04FRR, 8C04FRR2	11/01/06-10/08/07	Seats were equipped with a large supplemental "body pillow" that partially obscures the child airbag warning label on the seat pad. Graco will instruct users to discard the supplemental pillows since they are provided for comfort only. Contact mfg. for additional information.
406)	GT 1000 All	1/85-1/86	Crash test failure. Call mfg. for repair info.
407)	SnugRide 7493, 7497, 7499, 841101, 841102, 841103, 841203, 8412T02, 8457, 8458, 8459, 8460, 8462, 8471, 8472, 8473, 8474, 8476, 8477, 8478	08/31/99-02/28/02	May be missing 1 or 2 metal hooks and their retainer pins on the base of the carrier shell or the "U" shaped bars on the carrier shell that are used to attach the carrier to the base. If the hooks, pins or "U" bars are missing, the carrier may not be securely attached to the base and the carrier could detach from the base in the event of a sudden stop or crash. Call Graco to receive a free replacement seat or base. NOTE: All affected model numbers may also begin with the letter "A" and/or also be followed by letters.
408)	SnugRide 8402, 8402L, 8403x, 8412, 8442x, 8443, 8443L, 8444, 8444L, 8446, 8446L, 8447, 8447L, 8448, 8448L, 8457, 8458, 8459, 8463x, 8464, 8470, 8471, 8478, 8601, 8602x, 8603M, 8605x, 8607x, 8608D, C844342	03/01/02-03/08/03	May have missing hardware used to attach the carrier to the base. Contact mfg. at 866-473-0163 or www.gracobaby.com for inspection and repair information. All models can safely be installed without the base. [NOTE: The initial 03/12/03 recall campaign for this problem included models manufactured through 03/06/03. A recall extension announced 08/13/03 added models manufactured through 03/08/03.]
409)	SnugRide 8609x, 8616x, 8643x, 8645x, 8646x	08/01/06-06/30/07	The backing of the seat pad may pull away from the seams in an area reachable to the child occupant, exposing the pad filling and posing a potential choking hazard. Contact mfg. For repair kit.
<b>International</b>			
<b>ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY &amp; REPLACE</b>			
410)	Astroseat All	12/80-7/81	Buckle. Destroy & replace seat.
<b>Kolcraft</b>			
<b>ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY &amp; REPLACE</b>			
411)	Automate 180-600, 180-601	Pre 4/93	Buckle. Call mfg. for repair info.
412)	Carter Travel 5 13833, 13842, 13852	5/96-9/96	Crash test failure of buckle. Call mfg. for repair info.
413)	Dial-A-Fit 180-200, 180-300	1/87-8/89	Upholstery clips. Call mfg. for repair info.
414)	Dial-A-Fit 180-200, 180-300	10/88-8/89	Crash test failure. Call mfg. for repair info.
415)	Dial-A-Fit II 180-600	11/90-8/91	Crash test failure. Call mfg. for repair info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**



For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Kolcraft (continued)**

416)	Infant Car Seat	1383x	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
417)	Infant Restraint	43xxx	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
418)	Infant Rider	138xx, 368xx	3/96-8/96	Crash test failure of buckle. Call mfg. for repair info.
419)	Infant Rider	1312x, 1382x, 1383x, 368xx	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
420)	Flip 'N' Go	19127 thru 19130	1/85-3/87	Shield. Call mfg. for repair info.
421)	Flip 'N' Go II	19127	1/85-3/88	Shield. Call mfg. for repair info.
422)	Perfect Fitt	180-100, 180-150	Pre 4/90	Upholstery clips. Call mfg. for repair info.
423)	Perfect Fitt	180-150, 180-200	3/89-10/90	Crash test failure. Call mfg. for repair info.
424)	Perfect Fitt	180-200	Pre 10/90	Upholstery. Call mfg. for repair info.
425)	Performa	All	3/96-10-96	Upholstery. Call mfg. for repair info.
426)	Performa	All	1/96-7/97	Buckle release force. Call mfg. for repair info.
427)	Playskool Car Seat	140-155, 180-400	12/89-8/90	Upholstery. Call mfg. for repair info.
428)	Playskool Car Seat	77001, 77002	1/91-6/93	Buckle. Call mfg. for repair info.
429)	Playskool Infant Car Seat	77005, 77007	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
430)	Plus 4	138xx, 368xx	3/96-8/96	Crash test failure of buckle. Call mfg. for repair info.
431)	Plus 4	1382x, 1383x, 1384x, 368xx	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
432)	Plus 5	138xx, 368xx	3/96-8/96	Crash test failure of buckle. Call mfg. for repair info.
433)	Plus 5	13833, 13842, 13852	5/96-9/96	Crash test failure of buckle. Call mfg. for repair info.
434)	Plus 5	1382x, 1383x, 1384x, 1385x, 368xx	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
435)	Rock 'N' Ride	13123	2/85-6/85	Plastic shell. Call mfg. to replace seat.
436)	Rock 'N' Ride	131-101	Pre 3/90	Upholstery clips. Call mfg. for repair info.
437)	Secura	43xxx	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
438)	Secure Fit	All	1/96-7/97	Buckle release force. Call mfg. for repair info.
439)	Travel About	138xx, 368xx	3/96-8/96	Crash test failure of buckle. Call mfg. for repair info.
440)	Travel About	13833, 13842, 13852	5/96-9/96	Crash test failure of buckle. Call mfg. for repair info.
441)	Travel-About	1382x, 1383x, 1384x, 1385x	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
442)	Traveler 700	All	11/01/94-12/31/95	Voluntary action: Buckle concerns. Call mfg. for repair info.
443)	Traveler 700	150-100	1/91-8/91	Cracks in plastic. Call mfg. to replace seat.
444)	Traveler 700	All	1/91-6/93	Rusting of buckle. Call mfg. for repair info.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model # ("X" = more numbers or letters follow)	Customer assistance Mfg Date	Problem Type and Consumer Action
<b>Lin Lih/MCP Ent.</b>		<b>ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM DISCONTINUED - DESTROY &amp; REPLACE</b>	
445)	Lin Lih All	ALL	Counterfeit seat. Call NHTSA: 800-424-9393
446)	Lin Lih 180-200, 180-300	10/88-8/89	Crash test failure. Call NHTSA: 800-424-9394
<b>Maxi-Cosi (Dorel)</b>		<b>Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com</b>	
447)	Mico 22-371, 22-372 Mico (base) 22-515	07/01/07- 02/17/08	Attachment difficulties between the infant carrier and the base may lead to the carrier being improperly mounted to the base. Contact mfg. for replacement base.
448)	Mico 22-371 HFL, 22-371 JUC, 22-371 LMD, 22-371 ORE, Mico (base) 22-371 PNG, 22-372 TTH 22-515 BLK	02/18/08- 06/28/08	Attachment difficulties between the infant carrier and the base may lead to the carrier being improperly mounted to the base. Contact mfg. for repair kit. NOTE: This is an extension of an earlier recall.
449)	Mico 22371x, 22372x	05/01/08- 04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
450)	Priori 22476x, 22486x	05/01/08- 04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
<b>Mia Moda</b>		<b>866-642-6632 - www.miamodainc.com</b>	
451)	Viva 5000 (seat), 5001 (base)	12/19/06- 02/06/07	The lower anchor connector adjuster assembly may interfere with the connection of the infant carrier to the restraint base when installed using LATCH. Installation with seat belt is not affected. In addition, registration cards were not provided with the Viva or separately sold bases. Contact mfg. For repair kit and to register CR with mfg.
452)	Viva 5000 (seat), 5001 (base), 5050 (seat), 5051 (base), Viva Supreme 5070 (seat), 5071 (base) 5080 (seat), 5081 (base)	12/01/06- 05/31/09	Sharp edges on the harness splitter plate can cut the harness. Also, the base could crack in a crash. Contact mfg. at 877-546-8437 for a full refund. Mia Moda is urging parents/caregivers to discontinue use of the seat until it can be replaced. According to Lerado/Mia Moda, there have been no injuries reported due to these problems and this is a voluntary precaution they are taking.
<b>Mercedes-Benz USA</b>		<b>800-367-6372 - www.mbusa.com</b>	
453)	Booster BQ6910157, BQ6910163	02/01/97- 07/31/99	BabySmart airbag deactivation device may not automatically deactivate the passenger airbag. Contact mfg. for free replacement seat and instructional video.
454)	Infant Restraint BQ6910155	02/01/97- 07/31/99	BabySmart airbag deactivation device may not automatically deactivate the passenger airbag. Contact mfg. for free replacement seat and instructional video.
455)	Kiddy TopSafe B66868203 (mfg. by B66868204 Sicartex) B66868209	03/01/03- 11/30/03	Lower LATCH attachment may not be strong enough to hold in the event of a crash. Immediately replace with another model and return Kiddy Top seat to Mercedes-Benz dealer for refund. Install with vehicle seat belt until replacement is obtained. Contact Mercedes-Benz for further information.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

<b>List No.</b>	<b>Manufacturer Model # ("X" = more numbers or letters follow)</b>	<b>Customer assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Peg Perego USA</b>		<b>877-737-3468 / 219-482-8191 - www.perego.com</b>	
456)	Jacadi IMCB00JA57RJ31JU31	07/01/07-03/14/08	The plastic adjustment cover of affected models could have exposed sharp edges that could cause cuts, scratches, or abrasions on the feet or legs of bare-footed infants. Does not affect safety as car seat. Contact mfg. for a free repair kit.
457)	Primo Viaggio CS00MU1, CS00US1, CS00US8	02/01/01-06/10/01	The latch mechanism securing the seat to the base does not completely engage on a small number of seats due to improper positioning of the metal reinforcement bracket. Call mfg. for repair info. Note: Primo Viaggio infant seat sold separately and with strollers as part of Pliiko and Primo Viaggio Travel Systems.
458)	Primo Viaggio CS00MU1, CS00US1, CS00US8, LV34USL, LV34USN, LN34S09, LN34S10, ST33USL, ST33USN, ST38USL, ST38USN, AL33USL, AL33USN, AL34USN, AL34USL	05/20/01-02/15/02	The harness adjustment/locking mechanism may not fully lock and allow the harness to slip. The strap tension adjuster cover of affected models have a red circle around a dark button. Contact mfg, for full identification and repair information. Note: Primo Viaggio infant seat sold separately and with strollers as a part of Pliiko, Primo Viaggio, and Atlantico Travel Systems.
459)	Primo Viaggio SIP 30/30 32MD41KN41, 35CR13BU13, 35CR13PL46, 35CR24BU24, 35TL49KN53, 35TL53KN46, 61FG13ST53, 61FG53ST49, 61FG53ST64, 61ST13IC53, 61ST34IC53, 61ST48IC53	07/01/07-03/14/08	The plastic adjustment cover of affected models could have exposed sharp edges that could cause cuts, scratches, or abrasions on the feet or legs of bare-footed infants. Does not affect safety as car seat. Contact mfg. For a free repair kit. Note: Affected model numbers begin with IMUN00US.
<b>Playskool</b>		<b>Contact Kolcraft: 800-453-7673</b>	
460)	Car Seat 140-155, 180-400	12/89-8/90	Upholstery. Call Kolcraft
461)	Car Seat 77001, 77002	1/91-6/93	Buckle. Call Kolcraft
462)	Infant Car Seat 77005, 77007	1/93-6/99	Carrier handle can release and allow the seat to rotate. Does not affect safety as car seat. Call mfg. for repair info.
<b>Pride Trimble/Virco</b>		<b>800-521-5198</b>	
463)	Click-n-Go 890, 891, 892	2/86-10/87	Crash test failure. Call mfg. to replace seat.
464)	Click-n-Go 890, 891, 892	1/88-4/89	Crash test failure. Call mfg. to replace seat.
465)	Pride Ride 832	1/88-4/89	Crash test failure. Call mfg. to replace seat.
<b>Questor</b>		<b>Contact Evenflo: 800-233-5921</b>	
466)	Kantwet Car Seat All	5/69-3/73	May pinch child's fingers. Call mfg. for repair info.
<b>Recaro</b>		<b>888-973-2276 / 800-873-2276 / 248-364-3818 / www.recaropromotion.com</b>	
467)	Como 331.00.xxx	Pre-09/17/07	Consumer Advisory - Not a Recall: Lap and shoulder belt guide (previously referred to as "lock-off") may not hold belt webbing snugly enough to prevent belt from loosening. Contact mfg. for locking clip and instructions included as a part of the consumer advisory.
468)	Como 331.00.xxx	Pre-12/18/07	The harness may become disconnected from the harness connector when a child is placed in or removed from the child seat. Contact mfg. for repair kit.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Recaro (continued)**

469)	Como	331.00.xxx, 331.01.xxx	11/01/07-02/16/09	The front harness adjuster strap may slip within the adjuster/lock that controls tightness of the harness and may prevent the harness from staying properly tight. Contact mfg. for free replacement seat. NOTE: Models with a green dot above the bar code on the model # sticker are OK to use.
470)	Signo	331.00.xxx	Pre-12/18/07	The harness may become disconnected from the harness connector when a child is placed in or removed from the child seat. Contact mfg. for repair kit.
471)	Signo	330.00.xxx, 330.01.xxx	11/01/07-02/16/09	The front harness adjuster strap may slip within the adjuster/lock that controls tightness of the harness and may prevent the harness from staying properly tight. Contact mfg. for free replacement seat. NOTES: This date range is an expansion of the initial date range (02/01/08-09/30/08) for this recall. Models with a green dot above the bar code on the model # sticker are OK to use.

**Renolux (FBS)****ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY & REPLACE**

472)	GT 1000	All	8/88-10/88	Buckle/recline angle. Destroy & replace seat.
473)	GT 2000	All	8/88-10/88	Buckle/recline angle. Destroy & replace seat.
474)	GT 2000	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
475)	GT 2000	All	5/89-6/93	Flammability of upholstery. Destroy & replace seat.
476)	GT 4000	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
477)	GT 4000	All	5/89-6-93	Flammability of upholstery. Destroy & replace seat.
478)	GT 5000	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
479)	GT 5000	All	5/89-6-93	Flammability of upholstery. Destroy & replace seat.
480)	GT 5000 Turn A Tot	All	2/90-4/91	Test failure/upholstery. Destroy & replace seat.
481)	GT 5000 Turn A Tot	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
482)	GT 5000 Turn A Tot	All	5/89-6-93	Flammability of upholstery. Destroy & replace seat.
483)	GT 5500	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
484)	GT 5500	All	5/89-6-93	Flammability of upholstery. Destroy & replace seat.
485)	GT 7000	All	All	Remote may overheat/ fire hazard. Destroy & replace seat.
486)	GT 7000	All	1/92-1/93	Foam padding failed HIC (head injury) limits. Destroy & replace seat.
487)	GT 7000	All	5/89-6-93	Flammability of upholstery. Destroy & replace seat.

**Safeline Kids****800-829-1625 - www.tripleplayproducts.com**

488)	Sit'n'Stroll	3240	6/9/97-8/9/97	Air bag labels. The air bag warning label was omitted from the seat cover. Contact Mfg. for new seat cover that has the required air bag warning label.
489)	Sit'n'Stroll	3240	11/1/96-6/30/99	Labels recommend use rear-facing for children up to 25 pounds. Contact Mfg. for new labels to be placed over the existing labels. New labels recommend use rear-facing for children up to 22 pounds.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Safeline Kids (continued)**

490)	Sit'n'Stroll	2240	04/01/01-10/01/01	The FAA certification statement on label is in yellow lettering instead of the required RED lettering. Flight attendants may not allow its use on an airplane. Contact mfg. for replacement label.
491)	Sit'n'Stroll	2003	09/01/02-10/21/03	Child's head may move too far forward in a crash when lower forward-facing belt path or shoulder and buckle pads are used. Remove and discard shoulder and buckle pads and use upper forward-facing belt path only. Contact mfg. for revised instructions and labels.

**Safety 1st (Dorel)****Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141  
www.djgusa.com**

492)	Alpha Elite	All Models	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
493)	Alpha Omega Alpha Omega Elite	22151 22455	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
494)	Alpha Omega All-N-1 Alpha Omega Elite	22152x, 22159x, 22172x, 22177x, 22178x, 22185x, 22188x, 22195x, 22412x, 22456x, 22465x, 22469x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
495)	Alpha Sport	All Models	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
496)	Avenue	22439x, 22449x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
497)	Designer 22	02-621-SAL, 02-620-xxx	01/03/02-02/13/02	Plastic handle can unexpectedly release from the carrying position when used as a carrier. Does not affect safety as a child restraint. Contact mfg. for repair kit.
498)	Designer 22	22-325 xxx GB1B	08/19/03-10/20/04	Harness can loosen if not properly tightened. Contact mfg. for free repair kit. Parents should continue to use the seat while waiting to receive/install the repair kit but are advised to make sure that the seat is properly adjusted while in use. NOTE: Models involved were sold only as travel systems (with a stroller) and any line code other than GB1B in the model # is not included in the recall.
499)	Enspira	22450, 22451, 22452, 22453, 22480, 22481	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
500)	Enspira	22453x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
501)	Infant Car Seat	22-057 CLN, 22-057 DBY, 22-057 HRT, 22-057 LPH, 22-085 DWA, 22-085 LYN, 22-095 RBK, 22-322 HRR, 22-322 KDL, 22-322 LXI, 22-322 MAI, 22-322 OLY, 22-322 PRS, 22-322 PTK, 22-325 COB, 22-325 PAC, 22-380 LGA, 22-380 MSA, 22-627 WAV	01/06/08-04/06/09	The child restraint carry handle can loosen and come off posing a fall hazard to infants. The safety as a child restraint is not affected. Do not use handle until repaired. Contact mfg. for free repair kit. NOTE: Only those models sold as a part of the Eurostar, Explorer, Lite Wave, Sojourn, and Vector Travel Systems are affected.

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Safety 1st (continued)**

502)	Intera	22460	11/01/03-12/31/05	There is a potential for the harness adjustment strap to loosen during use. Contact mfg. for free repair kit.
503)	OnBoard	22077x, 22078x, 22356x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
504)	Prospect	22580x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
505)	Uptown	22475x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.
506)	Vantage Vantage Point/ Surveyor Vantage Hiback	22553x, 22554x, 22560x, 22561x, 22564x, 22567x, 22574x	05/01/08-04/30/09	Harness locking and release button does not always return to its locked position and could result in a loose harness, increasing the risk of being injured a crash. Contact mfg. for repair kit.

**Snug Seat****800-336-7684 - [www.snugseat.com](http://www.snugseat.com)**

507)	Gorilla	200-1000	07/26/02-01/15/03	A washer in tether anchor kit does not meet corrosion requirements of FMVSS 213. Contact mfg. for replacement kit # FW-50250-12-ZY
------	---------	----------	-------------------	--

**Snug Seat (continued)**

508)	Spelcast	600-1000	07/26/02-01/15/03	A washer in tether anchor kit does not meet corrosion requirements of FMVSS 213. Contact mfg. for replacement kit # FW-50250-12-ZY
509)	Traveller Plus (Mfg. by Britax for Snug Seat)	E9L32	Pre-07/24/04	The adjuster strap may slip within the metal buckle that controls the tightness of the shoulder harness and may allow the harness to loosen. Contact Britax at 800-683-2045 or 704-409-1700 for repair kit.

**Strolee****ALL MODELS OLDER THAN 10 YEARS - NO LONGER IN BUSINESS - DESTROY & REPLACE**

510)	Wee Care	All	Pre 4/80	Crash test failure. Destroy & replace seat.
511)	Wee Care	599	12/80-5/81	Upholstery. Destroy & replace seat.
512)	Wee Care	609, 610	ALL	Plastic shell. Destroy & replace seat.
513)	Quick Click	605	ALL	Plastic shell. Destroy & replace seat.
514)	GT 3000	All	87/88	Crash test failure. Destroy & replace seat.

**Team-Tex America****877-912-1313**

515)	Babyride	374099	08/31/06-10/23/06	Belt routing label with "horizontal reference line" was incorrectly placed on the CR. Contact mfg. for a correct label and placement instructions. NOTE: According to Team-Tex America, all seats that were affected by this recall were caught and corrected before being purchased by consumers and thus should not be found in use.
------	----------	--------	-------------------	--

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

List No.	Manufacturer Model Name	Model # ("X" = more numbers or letters follow)	Mfg Date	Customer assistance Problem Type and Consumer Action
----------	-------------------------	--	----------	--

**Team Tex America (continued)**

516)	Babyride	374199	12/18/08	The belt routing label with the "horizontal reference line" for determining the correct recline angle is incorrectly placed on the child restraint. Contact mfg. for replacement label and instructions.
------	----------	--------	----------	--

**TriplePlay Products  
(See Safeline Kids also)****800-829-1625 - [www.tripleplayproducts.com](http://www.tripleplayproducts.com)**

517)	Sit'n'Stroll	4002	05/05/08	The webbing used in the center adjuster for the harness fails to comply with the initial breaking strength requirements of FMVSS 213. Contact mfg. for repair kit and instructions. NOTE: According to TriplePlay, the only units affected were a small number of seats manufactured on May 5, 2008 and sold through their website. All purchasers are being contacted and notified of this recall.
------	--------------	------	----------	---

**TRW****ALL MODELS OLDER THAN 10 YEARS - REPLACEMENT PROGRAM  
DISCONTINUED - DESTROY & REPLACE**

518)	Infant Love Seat	All	81/82	Plastic shell may develop cracks. Destroy & replace seat.
519)	Child Love Seat	All	3/84-11/84	Plastic shell may develop cracks. Destroy & replace seat.

**Volvo****800-458-1552 / 800-221-9136 / 201-768-7300**

520)	ALL SEATS	All	Thru 12/88	Buckle. Call mfg. for refund info.
------	-----------	-----	------------	------------------------------------

**XSCi****800-630-6850 / 719-593-8881**

521)	Pioneered ACIS	None*	02/01/02- 03/07/02	Exceeds the maximum head excursion criteria of FMVSS 213. In a crash, the cradle can detach from the deflector base. Contact mfg for replacement information (replacements produced by an alternate mfg.) *No model number is associated, but affects serial numbers 01C-000000002 to 01C-000000108. [NHTSA No.: 02E-024] **NOTE: According to XSCi, all seats that were affected by this recall have been returned (as of May 8, 2002) and thus should not be found in use.*
------	----------------	-------	-----------------------	--

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

*This page intentionally left blank for 2-sided printing/copying*

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

OLDER MODEL LIST

---

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**



Index of Recalls and Safety Notifications for Older Model List

For the model numbers "x" = more numbers or letters follow.

Model numbers and model names for car seats under recall are followed by their index number which corresponds to the "List No." for each listing. If the model number is not found, check the model name also. Model numbers are not available for all model names.

Note: Dorel Juvenile Group products are indexed under each individual product line (e.g., Cosco) as well as under "Dorel."

<b>Alcot (Childcare)</b>		# 960. .... 216, 217	Regent. .... 233, 234
Child Love Seat. .... 201		# 961. .... 216, 217	Roundabout. .... 235
		Galaxy 2000. .... 216, 217	Super Elite. .... 236, 237
<b>All Our Kids</b>			Traveller Plus. .... 238
# 600. .... 202	<b>Beatrix Potter (Dorel)</b>		Wizard. .... 239
# 602. .... 203	# 02-620-xxx. .... 218		
Little Cargo Vest. .... 202, 203	# 02-621-SAL. .... 218		<b>Century</b>
	Designer 22. .... 218		# 11-564. .... 258
<b>Alpha Elite (Dorel)</b>			# 11-565. .... 258
# 22148x. .... 205	<b>Bertini (Dorel)</b>		# 11-570. .... 257, 258
# 22149x. .... 205	# 22346x. .... 219		# 11-575. .... 258
# 22158x. .... 205	SureFit. .... 219		# 11-576. .... 258
# 22331 BLA. .... 206, 207	<b>Bolform Corp.</b>		# 11-578. .... 258
# 22332 RLA. .... 206, 207	# 84E-019. .... 220		# 11-595. .... 258
# 22459x. .... 205	Buckle-Up Harness. .... 220		# 11-597. .... 257, 258
# 22462x. .... 204			# 11-598. .... 258
Alpha Luxe. .... 204	<b>Britax</b>		# 11-599. .... 258
Alpha Omega All-N-1. .... 205	# 101. .... 226		# 11-600. .... 257, 258
Alpha Omega Elite. .... 205	# 161. .... 235		# 11-650. .... 257
Comfort Infant Seat. .... 206, 207	# E902228. .... 221		# 12-565. .... 277
<b>Alpha Sport (Dorel)</b>	# E9031. .... 236, 237		# 4100. .... 240, 241
# 22452x. .... 208	# E906. .... 232		# 4153. .... 242
# 22458x. .... 208	# E9L06. .... 232		# 4163. .... 242
# 22546x. .... 209	# E9L07. .... 239		# 4180. .... 242
# 22547x. .... 209	# E9L14. .... 223, 224		# 4200. .... 243, 244, 245, 246
Enspira. .... 208	# E9L20. .... 224		# 4210. .... 243, 244, 245, 246
Vantage. .... 209	# E9L30. .... 229, 230, 231		# 4214. .... 243, 244, 245, 246
	# E9L32. .... 238		# 4223. .... 243, 244, 245, 246
<b>American Motors</b>	# E9L3998. .... 234		# 4235. .... 243, 244, 245, 246
Child Love Seat. .... 211	# E9L39x. .... 233		# 4253. .... 247, 248, 249
Infant Love Seat. .... 210	# E9L47. .... 225		# 4261. .... 248, 249
	# E9L5490. .... 228		# 4263. .... 247, 248, 249
<b>Baby Trend</b>	# E9L54E7. .... 227, 228		# 4265. .... 247, 248, 249
# 6400. .... 213	# E9L54H6. .... 227		# 4266. .... 248, 249
# 6439. .... 212	# E9L54H7. .... 227		# 4300. .... 250
# 6448. .... 212	# E9L54M6. .... 227		# 4302. .... 250
# 6481. .... 212	# E9L57. .... 222		# 4303. .... 250
Rigid Latch-Loc. .... 212	# E9L80. .... 224		# 4310. .... 250
Rigid Latch-Loc Base. .... 213	# E9W06. .... 232		# 4323. .... 250
	Advantage. .... 221		# 4334. .... 250
<b>Babyhood Industries</b>	Boulevard. .... 222		# 4335. .... 250
# 810. .... 214	Companion. .... 223, 224		# 4353. .... 252, 253, 255
# 8200. .... 215	Decathlon. .... 225		# 4365. .... 252, 253, 254, 255
Baby-Sitter. .... 215	Freeway. .... 226		# 4365DT. .... 251
Wonda Chair. .... 214	Frontier. .... 227, 228		# 4366. .... 251, 252, 253, 254, 255
	Husky. .... 229, 230		<b>Century (continued)</b>
<b>Basic Comfort</b>	Marathon. .... 231, 232		# 4367. .... 254, 255
			# 4368. .... 252, 253, 254, 255

Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

# 4369.	254, 255	# 4750.	280		
# 4380.	254, 256	# 4875.	272	<b>Cosco</b>	
# 4381.	254	# 4885.	273	# 02-014-EMF.	319
# 4400.	259, 260	100.	240, 241	# 02-014-GDM.	319
# 4434.	259, 260	1000 STE.	242	# 02-015-PDL.	319
# 4436.	259, 260	200.	243, 244, 245, 246	# 02-084.	318, 321
# 4446.	259, 260	2000 STE.	247, 248, 249	# 02-086.	301
# 4450.	261, 262, 264, 265	300.	250	# 02-090.	315
# 4460.	261, 262, 263, 264, 265	3000 STE.	251, 252, 253, 254, 255	# 02-094.	321
# 44612.	275	3500 STE.	256	# 02-096.	321
# 44622.	271	4-In-1.	257, 258	# 02-190.	317
# 44630.	271	400XL.	259, 260	# 02-290.	316
# 44631.	271	5000 STE.	261, 262, 263, 264, 265	# 02-331.	292
# 44662.	271	5500 STE.	266	# 02-332.	292
# 4470.	262, 263, 264, 265	580.	267, 268	# 02-404.	321
# 44709.	281	Accel.	269	# 02-514-BWE.	320
# 4475.	261, 262, 263, 264, 265	Affinity.	270	# 02-518-NDF.	320
# 4476.	263, 264	Bravo.	271	# 02-531.	292
# 4480.	263, 266	Brevera Contour.	272	# 02-533.	292
# 4490.	263, 266	Brevera Premiere.	273	# 02-537.	292
# 4500.	278	Child Love Seat.	274	# 02-584-OXF.	320
# 4510.	278	Encore.	275	# 02-665.	299
# 45100.	269	Infant Car Seat.	276, 277	# 02-667.	326
# 4513.	277	Infant Love seat.	278	# 02-719 ARQ.	303
# 4515.	277	Smart Fit.	279	# 02-727.	299
# 4516.	277	Smart Move.	280, 281	# 02-728.	299
# 4518.	277			# 02-729.	299
# 4520.	278	<b>Chicco</b>		# 02-729 TED.	298
# 45200.	269	# All.	282	# 02-731.	299
# 4525.	279	Cortina Travel System.	282	# 02-732.	299
# 4535.	276	Key Fit.	282	# 02-733.	299
# 4551.	277	Key Fit 30.	282	# 02-750.	299
# 4557.	277			# 02-751.	297, 299
# 4558.	277	<b>Chrysler</b>		# 02-753.	326
# 4559.	277	Child Love Seat.	283	# 02-755.	299
# 4560.	276			# 02-756.	299, 326
# 45600.	269	<b>Collier-Keyworth</b>		# 02-757.	299
# 4564.	277	Co-Pilot.	284	# 02-758.	326
# 4565.	276, 277	Commuter.	286	# 02-759.	326
# 4566.	277	Safe and Sound II.	285	# 02-760.	326
# 4568.	277			# 02-761.	326
# 4569.	277	<b>Combi</b>		# 02-762.	326
# 45700.	269	# 8065.	288	# 02-763.	326
# 4575.	270, 277	# 8074.	288	# 02-764.	326
# 4576.	277	# 8086.	288	# 02-765.	326
# 4580.	268	# 8087.	289	# 02-770.	326
# 4581.	267, 268	# 8100.	287	# 02-771.	326
# 4583.	267, 268	# 8520.	288	# 02-772.	326
# 4585.	267, 268	# 8815.	290	# 02-774.	299
# 4589.	277	Avatar.	287	# 02-790.	308
# 4590.	276	Centre.	288	# 02-821.	321
# 4591.	277	Shuttle.	289	# 02-890.	308
# 4593.	277	Zeus Turn.	290	# 02014.	322
# 4594.	277			# 02015.	322
# 4595.	277	<b>Compass Baby</b>		# 02019.	322
# 4597.	277	# 1420 ARD.	291	# 02084.	322
# 4600.	274	# 1420 FUO.	291	# 02094.	322
# 4662.	275	# 1420 MAR.	291	<b>Cosco (continued)</b>	
		Infant Car Seat.	291	# 02114.	322

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

# 02332.	293	# 93100x.	324	# 02-537 (Cosco).	292
# 02409.	305	# 93111x.	324	# 02-537 (Eddie Bauer).	330
# 02442.	305, 306	# 93443.	306	# 02-555 (Cosco).	292
# 02443.	305, 306	# 93446.	323	# 02-555 (Eddie Bauer).	330
# 02445.	305	# 93504.	323	# 02-584-OXF (Cosco).	320
# 02448.	305, 306	# 93514.	306, 322	# 02-620-xxx (Beatrix Potter).	218
# 02449.	305	Alpha Omega.	292, 293, 294	# 02-620-xxx (Safety 1st).	497
# 02450.	305	Alpha Omega All-N-1.	296	# 02-621-SAL (Beatrix Potter).	218
# 02480.	305	Alpha Omega Elite.	294, 295	# 02-621-SAL (Safety 1st).	497
# 02495.	305	Arriva.	297, 298, 299	# 02-665 (Cosco).	299
# 02504.	322	Commuter.	301	# 02-667 (Cosco).	326
# 02514.	322, 323	Designer 22.	302	# 02-719 ARQ (Cosco).	303
# 02518.	322	Dream Ride.	303	# 02-727 (Cosco).	299
# 02519.	322, 323	DreamRide.	304	# 02-728 (Cosco).	299
# 02524.	322, 323	Hi Back Booster.	305	# 02-729 (Cosco).	299
# 02531.	293	High Rise Booster.	307	# 02-729 TED (Cosco).	298
# 02533.	293	Infant Car Seat.	300	# 02-731 (Cosco).	299
# 02537.	293	Lxry Sft Shld Auto Trac.	308	# 02-732 (Cosco).	299
# 02555.	293	Regal Ride.	309	# 02-733 (Cosco).	299
# 02584.	322	Safe and Easy.	312	# 02-750 (Cosco).	299
# 02803.	322	Safe and Snug.	313	# 02-751 (Cosco).	297, 299
# 02806.	322	Safe-T Mate.	311	# 02-753 (Cosco).	326
# 02821.	322	Safe-T-Shield.	310	# 02-755 (Cosco).	299
# 02825.	322	Sft Shld Auto Trac.	316	# 02-756 (Cosco).	299, 326
# 02935.	322	Soft Shield.	315	# 02-757 (Cosco).	299
# 181A.	310	Soft Shield Deluxe.	317	# 02-758 (Cosco).	326
# 181B.	310	Touriva.	318, 319, 320, 321, 322, 323, 324	# 02-759 (Cosco).	326
# 22-001FSM.	304	Turnabout.	326	# 02-760 (Cosco).	326
# 22-297.	307	Voyager Inf/Stroller.	327	# 02-761 (Cosco).	326
# 22-298.	307			# 02-762 (Cosco).	326
# 22-299.	307	<b>Disney (Dorel)</b>		# 02-763 (Cosco).	326
# 22-300 CSF.	300	# 22-305 NAB.	328	# 02-764 (Cosco).	326
# 22-300 FZN.	300	# 22-305 PPH.	328	# 02-765 (Cosco).	326
# 22-300 JJV.	300	# 22-355 LBF.	328	# 02-770 (Cosco).	326
# 22-300 OSF.	300	# 22-355 PWK.	328	# 02-771 (Cosco).	326
# 22-300 THD.	300	# 22-627 AWF.	328	# 02-772 (Cosco).	326
# 22-300 TWD.	300	Infant Car Seat.	328	# 02-774 (Cosco).	299
# 22-300-JOS GB1B.	302			# 02-790 (Cosco).	308
# 22100.	323	<b>Dorel</b>		# 02-821 (Cosco).	321
# 22100x.	324	# 02-014-EMF (Cosco).	319	# 02-890 (Cosco).	308
# 22111x.	324	# 02-014-GDM (Cosco).	319	# 02014 (Cosco).	322
# 22130x.	324	# 02-015-PDL (Cosco).	319	# 02015 (Cosco).	322
# 22139MON.	309	# 02-084 (Cosco).	318, 321	# 02019 (Cosco).	322
# 22150.	294	# 02-086 (Cosco).	301	# 02084 (Cosco).	322
# 22150x.	296	# 02-090 (Cosco).	315, 316	# 02094 (Cosco).	322
# 22154x.	295	# 02-094 (Cosco).	321	# 02114 (Cosco).	322
# 22155.	294	# 02-096 (Cosco).	321	# 02332 (Cosco).	293
# 22155x.	295	# 02-190 (Cosco).	317	# 02409 (Cosco).	305
# 22158x.	295	# 02-331 (Cosco).	292	# 02409 (Eddie Bauer).	339
# 22180.	294	# 02-331 (Eddie Bauer).	330	# 02442 (Cosco).	305, 306
# 22269.	294	# 02-332 (Cosco).	292	# 02442 (Eddie Bauer).	339
# 313.	312	# 02-332 (Eddie Bauer).	330	# 02443 (Cosco).	305, 306
# 323.	313	# 02-404 (Cosco).	321	# 02443 (Eddie Bauer).	339
# 423.	313	# 02-514-BWE (Cosco).	320	# 02445 (Cosco).	305
# 81A.	310	# 02-518-NDF (Cosco).	320	# 02445 (Eddie Bauer).	339
# 81B.	310	# 02-531 (Cosco).	292	# 02448 (Cosco).	305, 306
# 93084.	322	# 02-531 (Eddie Bauer).	330	# 02448 (Eddie Bauer).	339
# 93094.	322	# 02-533 (Cosco).	292	<b>Dorel (continued)</b>	
		# 02-533 (Eddie Bauer).	330	# 02449 (Cosco).	305

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

# 02449 (Eddie Bauer).....	339	# 22-355 LBF (Disney).....	328	# 22449x (Safety 1st).....	496
# 02450 (Cosco).....	305	# 22-355 PWK (Disney).....	328	# 22450 (Safety 1st).....	499
# 02450 (Eddie Bauer).....	339	# 22-371 (Eddie Bauer).....	447	# 22451 (Safety 1st).....	499
# 02480 (Cosco).....	305	# 22-371 HFL (Maxi-Cosi).....	448	# 22452 (Safety 1st).....	499
# 02480 (Eddie Bauer).....	339	# 22-371 JUC (Maxi-Cosi).....	448	# 22452x (Alpha Sport).....	208
# 02495 (Cosco).....	305	# 22-371 LMD (Maxi-Cosi).....	448	# 22453 (Safety 1st).....	499
# 02495 (Eddie Bauer).....	339	# 22-371 ORE (Maxi-Cosi).....	448	# 22453x (Safety 1st).....	500
# 02504 (Cosco).....	322	# 22-371 PNG (Maxi-Cosi).....	448	# 22455 (Safety 1st).....	493
# 02514 (Cosco).....	322, 323	# 22-372 (Eddie Bauer).....	447	# 22456x (Safety 1st).....	494
# 02518 (Cosco).....	322	# 22372 TTH (Maxi-Cosi).....	448	# 22458x (Alpha Sport).....	208
# 02519 (Cosco).....	322, 323	# 22-380 LGA (Safety 1st).....	501	# 22459x (Alpha Elite).....	205
# 02524 (Cosco).....	322, 323	# 22-380 MSA (Safety 1st).....	501	# 22460 (Safety 1st).....	502
# 02531 (Cosco).....	293	# 22-515 (Eddie Bauer).....	447	# 22462x (Alpha Elite).....	204
# 02533 (Cosco).....	293	# 22-515 BLK (Maxi-Cosi).....	448	# 22465x (Safety 1st).....	494
# 02537 (Cosco).....	293	# 22-625 xxx GB1B (Eddie Bauer).....	336	# 22469x (Safety 1st).....	494
# 02555 (Cosco).....	293	# 22-627 AWF (Disney).....	328	# 22475x (Safety 1st).....	505
# 02584 (Cosco).....	322	# 22-627 CGT (Eddie Bauer).....	340	# 22476x (Maxi-Cosi).....	450
# 02803 (Cosco).....	322	# 22-627 FRK (Eddie Bauer).....	340	# 22480 (Safety 1st).....	499
# 02806 (Cosco).....	322	# 22-627 KGS (Eddie Bauer).....	340	# 22481 (Safety 1st).....	499
# 02821 (Cosco).....	322	# 22-627 SNW (Eddie Bauer).....	340	# 22486x (Maxi-Cosi).....	450
# 02825 (Cosco).....	322	# 22-627 WAV (Safety 1st).....	501	# 224x (Cosco).....	325
# 02870 (Eddie Bauer).....	343	# 22-627 WPR (Eddie Bauer).....	340	# 22546x (Alpha Sport).....	209
# 02871 (Eddie Bauer).....	343	# 22-655 BYTE (Eddie Bauer).....	340	# 22547x (Alpha Sport).....	209
# 02875 (Eddie Bauer).....	343	# 22077x (Safety 1st).....	503	# 22553x (Safety 1st).....	506
# 02935 (Cosco).....	322	# 22078x (Safety 1st).....	503	# 22554x (Safety 1st).....	506
# 181A (Cosco).....	310	# 22100 (Cosco).....	323	# 22560x (Safety 1st).....	506
# 181B (Cosco).....	310	# 22100x (Cosco).....	324	# 22561x (Safety 1st).....	506
# 219x (Cosco).....	325	# 22111x (Cosco).....	324	# 22564x (Safety 1st).....	506
# 22-001FSM (Cosco).....	304	# 22130x (Cosco).....	324	# 22567x (Safety 1st).....	506
# 22-057 CLN (Safety 1st).....	501	# 22139MON (Cosco).....	309	# 22574x (Safety 1st).....	506
# 22-057 DBY (Safety 1st).....	501	# 22148x (Alpha Elite).....	205	# 22580x (Safety 1st).....	504
# 22-057 HRT (Safety 1st).....	501	# 22149x (Alpha Elite).....	205	# 225x (Cosco).....	325
# 22-057 LPH (Safety 1st).....	501	# 22150 (Cosco).....	294	# 22630xxx (Eddie Bauer).....	333, 334
# 22-085 DWA (Safety 1st).....	501	# 22150x (Cosco).....	296	# 22631xxx (Eddie Bauer).....	333, 334
# 22-085 LYN (Safety 1st).....	501	# 22151 (Safety 1st).....	493	# 22657x (Eddie Bauer).....	342
# 22-095 RBK (Safety 1st).....	501	# 22152x (Safety 1st).....	494	# 22740 (Eddie Bauer).....	331, 337
# 22-297 (Cosco).....	307	# 22154x (Cosco).....	295	# 22740x (Eddie Bauer).....	338
# 22-298 (Cosco).....	307	# 22155 (Cosco).....	294	# 22741x (Eddie Bauer).....	338
# 22-299 (Cosco).....	307	# 22155x (Cosco).....	295	# 22750 (Eddie Bauer).....	331, 332
# 22-300 CSF (Cosco).....	300	# 22158x (Alpha Elite).....	205	# 22755 (Eddie Bauer).....	331, 332
# 22-300 FZN (Cosco).....	300	# 22158x (Cosco).....	295	# 22755x (Eddie Bauer).....	335
# 22-300 JJV (Cosco).....	300	# 22159x (Safety 1st).....	494	# 22756 (Eddie Bauer).....	331, 332
# 22-300 OSF (Cosco).....	300	# 22172x (Safety 1st).....	494	# 22757 (Eddie Bauer).....	331, 332
# 22-300 THD (Cosco).....	300	# 22177x (Safety 1st).....	494	# 22758x (Eddie Bauer).....	335
# 22-300 TWD (Cosco).....	300	# 22178x (Safety 1st).....	494	# 22759x (Eddie Bauer).....	335
# 22-300-JOS GB1B (Cosco).....	302	# 22180 (Cosco).....	294	# 22770 (Eddie Bauer).....	331, 332
# 22-305 NAB (Disney).....	328	# 22185x (Safety 1st).....	494	# 22790x (Eddie Bauer).....	335
# 22-305 PPH (Disney).....	328	# 22188x (Safety 1st).....	494	# 22799x (Eddie Bauer).....	335
# 22-322 HRR (Safety 1st).....	501	# 22195x (Safety 1st).....	494	# 22880x (Eddie Bauer).....	341
# 22-322 KDL (Safety 1st).....	501	# 22269 (Cosco).....	294	# 229x (Cosco).....	325
# 22-322 LXI (Safety 1st).....	501	# 22331 BLA (Alpha Elite).....	206, 207	# 244x (Cosco).....	314
# 22-322 MAI (Safety 1st).....	501	# 22332 RLA (Alpha Elite).....	206, 207	# 313 (Cosco).....	312
# 22-322 OLY (Safety 1st).....	501	# 22346x (Bertini).....	219	# 323 (Cosco).....	313
# 22-322 PRS (Safety 1st).....	501	# 22356x (Safety 1st).....	503	# 423 (Cosco).....	313
# 22-322 PTK (Safety 1st).....	501	# 22371x (Maxi-Cosi).....	449	# 81A (Cosco).....	310
# 22-325 COB (Safety 1st).....	501	# 22372x (Maxi-Cosi).....	449	# 81B (Cosco).....	310
# 22-325 PAC (Safety 1st).....	501	# 22412x (Safety 1st).....	494	# 93084 (Cosco).....	322
# 22-325 xxx GB1B (Safety 1st).....	498	# 22439x (Safety 1st).....	496	<b>Dorel (continued)</b>	
				# 93094 (Cosco).....	322

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

Produced by: UNC Highway Safety Research Center - 800-672-4527 x2

Download this list &amp; sign up for email notification of updates:

Funded by: NC Governor's Highway Safety Program

buckleupnc.org/car-seat-recall-list

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

# 93100x (Cosco).....	324	Sidekick Booster (Cosco).....	314	# 22758x.....	335
# 93111x (Cosco).....	324	Soft Shield (Cosco).....	315	# 22759x.....	335
# 93443 (Cosco).....	306	Soft Shield Deluxe (Cosco).....	317	# 22770.....	331, 332
# 93446 (Cosco).....	323	SureFit (Bertini).....	219	# 22790x.....	335
# 93504 (Cosco).....	323	SureFit (Eddie Bauer).....	342	# 22799x.....	335
# 93514 (Cosco).....	306, 322	Touriva (Cosco).....	318, 322, 323, 324	# 22880x.....	341
# IC072x (Eddie Bauer).....	342	Touriva (Eddie Bauer).....	343	# IC072x.....	342
3-in-1 (Eddie Bauer).....	330, 331	Touriva 5-point (Cosco).....	320	3-in-1.....	330, 331
Alpha Elite (Safety 1st).....	492	Touriva Shield (Cosco).....	319	Alpha Omega.....	332
Alpha Luxe (Alpha Elite).....	204	Touriva T-Shield (Cosco).....	321	Alpha Omega Elite.....	332
Alpha Omega (Cosco).....	292, 293, 294	Trooper (Cosco).....	325	Comfort Infant Seat.....	333, 334
Alpha Omega (Eddie Bauer).....	332	Turnabout (Cosco).....	326	Deluxe 3-in-1.....	331, 335
Alpha Omega (Safety 1st).....	493	Uptown (Safety 1st).....	505	Deluxe Convertible.....	331
Alpha Omega All-N-1 (Alpha Elite).....	205	Vantage (Alpha Sport).....	209	Designer 22.....	336
Alpha Omega All-N-1 (Cosco).....	296	Vantage (Safety 1st).....	506	Enspira.....	337, 338
Alpha Omega All-N-1 (Safety 1st).....	494	Vantage Highback (Safety 1st).....	506	Hi Back Booster.....	339
Alpha Omega Elite (Alpha Elite).....	205	Vantage Point/Surveyor (Safety 1st).....	506	Infant Car Seat.....	340
Alpha Omega Elite (Cosco).....	294, 295	Voyager Inf/Stroller (Cosco).....	327	Prospect Adjustable Hiback Booster.....	341
Alpha Omega Elite (Eddie Bauer).....	332			SureFit.....	342
Alpha Omega Elite (Safety 1st).....	493, 494	<b>Downunder</b>		Touriva.....	343
Alpha Sport (Safety 1st).....	495	Kangaroo Booster.....	329		
Arriva (Cosco).....	297, 298, 299	<b>Eddie Bauer</b>		<b>Evenflo</b>	
Avenue (Safety 1st).....	496	# 02-331.....	330	# 200x.....	364
Comfort Infant Seat (Alpha Elite).....	206, 207	# 02-332.....	330	# 201.....	360
Comfort Infant Seat (Eddie Bauer).....	333, 334	# 02-531.....	330	# 202.....	356, 360
Commuter (Cosco).....	301	# 02-533.....	330	# 203x.....	361
Deluxe 3-in-1 (Eddie Bauer).....	331, 335	# 02-537.....	330	# 205x.....	361, 372, 373
Deluxe Convertible (Eddie Bauer).....	331	# 02-555.....	330	# 206.....	362
Designer 22 (Beatrix Potter).....	218	# 02409.....	339	# 207x.....	363
Designer 22 (Cosco).....	302	# 02442.....	339	# 210x.....	361, 373
Designer 22 (Eddie Bauer).....	336	# 02443.....	339	# 211x.....	364
Designer 22 (Safety 1st).....	497, 498	# 02445.....	339	# 219164.....	377
Dream Ride (Cosco).....	303	# 02448.....	339	# 219180.....	377
DreamRide (Cosco).....	304	# 02449.....	339	# 219186.....	377
Enspira (Alpha Sport).....	208	# 02450.....	339	# 219188.....	377
Enspira (Eddie Bauer).....	337, 338	# 02480.....	339	# 21940.....	377
Enspira (Safety 1st).....	499, 500	# 02495.....	339	# 219x.....	325, 351, 369
Hi Back Booster (Cosco).....	305	# 02870.....	343	# 221.....	366
Hi Back Booster (Eddie Bauer).....	339	# 02871.....	343	# 222.....	367
High Rise Booster (Cosco).....	307	# 02875.....	343	# 223.....	367
Infant Car Seat (Cosco).....	300	# 22-625 xxx GB1B.....	336	# 224x.....	325, 349, 350, 351, 369
Infant Car Seat (Disney).....	328	# 22-627 CGT.....	340	# 225x.....	325, 351, 369
Infant Car Seat (Eddie Bauer).....	340	# 22-627 FRK.....	340	# 227.....	381
Infant Car Seat (Safety 1st).....	501	# 22-627 KGS.....	340	# 228.....	371
Intera (Safety 1st).....	502	# 22-627 SNW.....	340	# 229x.....	325, 351, 368, 369
Lxry Sft Shld Auto Trac (Cosco).....	308	# 22-627 WPR.....	340	# 231.....	380
Mico (Maxi-Cosi).....	447, 448, 449	# 22-655 BYTE.....	340	# 232.....	382
OnBoard (Safety 1st).....	503	# 22630xxx.....	333, 334	# 242.....	348
Priori (Maxi-Cosi).....	450	# 22631xxx.....	333, 334	# 244x.....	314
Prospect (Safety 1st).....	504	# 22657x.....	342	# 264x.....	375, 376
Prospect Adjustable Hiback Booster (Eddie Bauer).....	341	# 22740.....	331, 337	# 272x.....	352
Regal Ride (Cosco).....	309	# 22740x.....	338	# 273x.....	352
Safe and Easy (Cosco).....	312	# 22741x.....	338	# 3021769Z.....	354
Safe and Snug (Cosco).....	313	# 22750.....	331, 332	# 3021854Z.....	354
Safe-T-Mate (Cosco).....	311	# 22755.....	331, 332	# 317xx.....	357
Safe-T-Shield (Cosco).....	310	# 22755x.....	335	# 320xx.....	357
Sft Shld Auto Trac (Cosco).....	316	# 22756.....	331, 332	# 359x.....	376
		# 22757.....	331, 332	# 3604098.....	358
				<b>Evenflo (continued)</b>	

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

# 378x.....	374	# 598xx.....	357	<b>Graco</b>	
# 379x.....	374	# 599xx.....	357	# 7493.....	407
# 389x.....	376	# 636x.....	378	# 7497.....	407
# 390.....	353	# 637x.....	378	# 7499.....	407
# 391.....	353	# 639001.....	365	# 8402.....	408
# 397xx.....	357	# 639002.....	365	# 8402L.....	408
# 398xx.....	357	410.....	344	# 8403x.....	408
# 401.....	366	Bobby Mac Champion.....	345	# 841101.....	407
# 402.....	366	Bobby Mac Deluxe.....	346	# 841102.....	407
# 403.....	366	Booster Seat.....	347, 348	# 841103.....	407
# 404.....	366	Champion.....	349, 350, 351	# 8412.....	408
# 405.....	366	Cozy Carry.....	352	# 841203.....	407
# 406.....	366	Discovery.....	353, 354	# 8412T02.....	407
# 407.....	366	Dyn-O-Mite.....	355, 356	# 8433x.....	403
# 408.....	366	Embrace.....	357	# 8442x.....	408
# 409.....	366	First Choice.....	358	# 8443.....	408
# 410.....	344	Infant Car Seat.....	359, 360	# 8443L.....	408
# 411.....	345	Joyride.....	361	# 8444.....	408
# 412.....	346	On My Way.....	362, 363, 364	# 8444L.....	408
# 414.....	346	On My Way base.....	365	# 8446.....	408
# 415.....	346	One-Step.....	366	# 8446L.....	408
# 416.....	346	One-Step Deluxe.....	367	# 8447.....	408
# 4176.....	367	Scout.....	368, 369	# 8447L.....	408
# 420.....	379	Seven Year Seat.....	370, 371	# 8448.....	408
# 435x.....	361	Sidekick.....	314	# 8448L.....	408
# 441.....	355, 356, 360	Travel Tandem.....	372, 373	# 8457.....	407, 408
# 442.....	355, 356, 360	Tribute.....	374	# 8458.....	407, 408
# 443.....	355, 356, 360	Triumph.....	375, 376	# 8459.....	407, 408
# 444.....	355, 356, 360	Trooper.....	325, 377	# 8460.....	407
# 445.....	355, 356, 360	Two-in-One.....	378	# 8462.....	407
# 446.....	355, 356, 360	Ultara I.....	379, 380	# 8463x.....	408
# 447.....	355, 356	Ultara II.....	381, 382	# 8464.....	408
# 447x.....	364			# 8470.....	408
# 448.....	355, 356, 360	<b>Fisher Price</b>		# 8471.....	407, 408
# 453.....	370, 371	# 79700.....	397	# 8472.....	407
# 454.....	370, 371	# 9100.....	383, 384, 385, 386, 387, 388, 389, 390, 391	# 8473.....	407
# 456.....	359, 360	# 9101.....	384, 385, 387, 388, 389, 390, 391	# 8474.....	407
# 458.....	359, 360	# 9104.....	392, 395, 396	# 8476.....	407
# 468x.....	352	# 9149.....	393	# 8477.....	407
# 469x.....	352	# 9173.....	394	# 8478.....	407, 408
# 470.....	347, 348	Booster.....	395, 396	# 8601.....	408
# 471.....	347, 348	Car Seat.....	383, 384, 385, 386, 387, 388, 389, 390, 391	# 8602x.....	408
# 476x.....	352	Delux Car Seat.....	392	# 8603M.....	408
# 477x.....	352	Infant Seat.....	393, 394	# 8605x.....	408
# 478x.....	352	Safe Embrace.....	397	# 8607x.....	408
# 480x.....	352			# 8608D.....	408
# 481x.....	352	<b>Ford</b>		# 8609x.....	409
# 492x.....	363	Infant Love Seat.....	398	# 8616x.....	409
# 493x.....	361			# 8629x.....	403
# 499x.....	364	<b>General Motors</b>		# 8630x.....	403
# 534.....	353	Child Love Seat.....	400	# 8631x.....	403
# 540xx.....	357	Infant Love Seat.....	399	# 8632x.....	403
# 548xx.....	357			# 8635x.....	403
# 549xx.....	357	<b>Gerry</b>		# 8639x.....	403
# 550xx.....	357	# 626.....	402	# 8643x.....	409
# 552.....	353	Guardian.....	401	# 8645x.....	409
# 556xx.....	357	Secure Ride.....	402	# 8646x.....	409
# 597xx.....	357			# 8C00x.....	403
				# 8C01x.....	403

## Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Graco (continued)**

# 8C02MRC2..... 404  
 # 8C02x..... 403  
 # 8C03x..... 403  
 # 8C04FRR..... 405  
 # 8C04FRR2..... 405  
 # 8C04x..... 403  
 # C844342..... 408  
 ComfortSport..... 403, 404, 405  
 GT 1000..... 406  
 SnugRide..... 407, 408, 409

**International**

Astroseat..... 410

**Kolcraft**

# 131-101..... 436  
 # 13123..... 435  
 # 1312x..... 419  
 # 1382x..... 419, 431, 434, 441  
 # 13833..... 412, 433, 440  
 # 1383x..... 416, 419, 431, 434, 441  
 # 13842..... 412, 433, 440  
 # 1384x..... 431, 434, 441  
 # 13852..... 412, 433, 440  
 # 1385x..... 434, 441  
 # 138xx..... 418, 430, 432, 439  
 # 140-155..... 427  
 # 150-100..... 443  
 # 180-100..... 422  
 # 180-150..... 422, 423  
 # 180-200..... 413, 414, 423, 424  
 # 180-300..... 413, 414  
 # 180-400..... 427  
 # 180-600..... 411, 415  
 # 180-601..... 411  
 # 19127..... 420, 421  
 # 19128..... 420  
 # 19129..... 420  
 # 19130..... 420  
 # 368xx..... 418, 419, 430, 431, 432, 434, 439  
 # 43xxx..... 417, 437  
 # 77001..... 428  
 # 77002..... 428  
 # 77005..... 429  
 # 77007..... 429  
 Automate..... 411  
 Carter Travel 5..... 412  
 Dial-A-Fit..... 413, 414  
 Dial-A-Fit II..... 415  
 Flip 'N' Go..... 420  
 Flip 'N' Go II..... 421  
 Infant Car Seat..... 416  
 Infant Restraint..... 417  
 Infant Rider..... 418, 419  
 Perfect Fitt..... 422, 423, 424  
 Performa..... 425, 426  
 Playskool..... 427, 428  
 Playskool Infant..... 429

Plus 4..... 430, 431  
 Plus 5..... 432, 433, 434  
 Rock 'N' Ride..... 435, 436  
 Secura..... 437  
 Secure Fit..... 438  
 Travel About..... 439, 440  
 Travel-About..... 441  
 Traveler 700..... 442, 443, 444

**Lin Lih/MCP**

# 180-200..... 446  
 # 180-300..... 446  
 Lin Lih..... 445, 446

**Maxi-Cosi**

# 22-371..... 447  
 # 22-371 HFL..... 448  
 # 22-371 JUC..... 448  
 # 22-371 LMD..... 448  
 # 22-371 ORE..... 448  
 # 22-371 PNG..... 448  
 # 22-372..... 447  
 # 22-372 TTH..... 448  
 # 22-515..... 447  
 # 22-515 BLK..... 448  
 # 22371x..... 449  
 # 22372x..... 449  
 # 22476x..... 450  
 # 22486x..... 450  
 Mico..... 447, 448, 449  
 Priori..... 450

**Mercedes-Benz**

# B66868203..... 455  
 # B66868204..... 455  
 # B66868209..... 455  
 # BQ6910155..... 454  
 # BQ6910157..... 453  
 # BQ691063..... 453  
 Booster Seat..... 453  
 Infant Restraint..... 454  
 Kiddy TopSafe..... 455

**Mia Moda**

# 5000..... 451, 452  
 # 5001..... 451, 452  
 # 5050..... 452  
 # 5051..... 452  
 # 5070..... 452  
 # 5071..... 452  
 # 5080..... 452  
 # 5081..... 452  
 Viva..... 451, 452  
 Viva Supreme..... 452

**Peg Perego**

# 32MD41KN41..... 459  
 # 35CR13BU13..... 459  
 # 35CR13PL46..... 459

# 35CR24BU24..... 459  
 # 35TL49KN53..... 459  
 # 35TL53KN46..... 459  
 # 61FG13ST53..... 459  
 # 61FG53ST49..... 459  
 # 61FG53ST64..... 459  
 # 61ST13IC53..... 459  
 # 61ST34IC53..... 459  
 # 61ST48IC53..... 459  
 # AL33USL..... 458  
 # AL33USN..... 458  
 # AL34USL..... 458  
 # AL34USN..... 458  
 # CS00MU1..... 457, 458, 459  
 # CS00US1..... 457, 458  
 # CS00US8..... 457, 458  
 # IMCB00JA57RJ31JU31..... 456  
 # LN34S09..... 458  
 # LN34S10..... 458  
 # LV34USL..... 458  
 # LV34USN..... 458  
 # ST33USL..... 458  
 # ST33USN..... 458  
 # ST38USL..... 458  
 # ST38USN..... 458  
 Jacadi..... 456  
 Primo Viaggio..... 457, 458  
 Primo Viaggio SIP 30/30..... 459

**Playskool**

# 140-155..... 460  
 # 180-400..... 460  
 # 77001..... 461  
 # 77002..... 461  
 # 77005..... 462  
 # 77007..... 462  
 Car Seat..... 460, 461  
 Infant Car Seat..... 462

**Pride Trimble/Virco**

# 832..... 465  
 # 890..... 463, 464  
 # 891..... 463, 464  
 # 892..... 463, 464  
 Click-n-Go..... 463, 464  
 Pride Ride..... 465

**Questor**

Kantwet Car Seat..... 466

**Recaro**

# 330.00.xxx..... 471  
 # 330.01.xxx..... 471  
 # 331.00.xxx..... 467, 468, 469, 470  
 # 331.01.xxx..... 469  
 Como..... 467, 468, 469  
 Signo..... 470, 471

**Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER**

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

<b>Renolux (FBS)</b>	# 22453. . . . .	499	# 4002. . . . .	517
GT 1000. . . . .	# 22453x. . . . .	500	Sit'n'Stroll. . . . .	517
GT 2000. . . . .	# 22455. . . . .	493	<b>TRW</b>	
GT 4000. . . . .	# 22456x. . . . .	494	Child Love Seat. . . . .	519
GT 5000. . . . .	# 22460. . . . .	502	Infant Love Seat. . . . .	518
GT 5000 Turn A Tot. . . . .	# 22465x. . . . .	494	<b>Volvo</b>	
GT 5500. . . . .	# 22469x. . . . .	494	All. . . . .	520
GT 7000. . . . .	# 22475x. . . . .	505	<b>XSCI</b>	
<b>Safeline Kids</b>	# 22480. . . . .	499	Pioneered ACIS. . . . .	521
# 3240. . . . .	# 22481. . . . .	499		
Sit'n'Stroll. . . . .	# 22553x. . . . .	506		
<b>Safeline Kids (see Triple Play also)</b>	# 22554x. . . . .	506		
# 2003. . . . .	# 22560x. . . . .	506		
# 2240. . . . .	# 22561x. . . . .	506		
# 3240. . . . .	# 22564x. . . . .	506		
Sit'n'Stroll. . . . .	# 22567x. . . . .	506		
<b>Safety 1st (Dorel)</b>	# 22574x. . . . .	506		
# 02-620-xxx. . . . .	# 22580x. . . . .	504		
# 02-621-SAL. . . . .	22439x. . . . .	496		
# 22-057 CLN. . . . .	Alpha Elite. . . . .	492		
# 22-057 DBY. . . . .	Alpha Omega. . . . .	493		
# 22-057 HRT. . . . .	Alpha Omega All-N-1. . . . .	494		
# 22-057 LPH. . . . .	Alpha Omega Elite. . . . .	493, 494		
# 22-085 DWA. . . . .	Alpha Sport. . . . .	495		
# 22-085 LYN. . . . .	Avenue. . . . .	496		
# 22-095 RBK. . . . .	Designer 22. . . . .	497, 498		
# 22-322 HRR. . . . .	Enspira. . . . .	499, 500		
# 22-322 KDL. . . . .	Infant Car Seat. . . . .	501		
# 22-322 LXI. . . . .	Intera. . . . .	502		
# 22-322 MAI. . . . .	OnBoard. . . . .	503		
# 22-322 OLY. . . . .	Prospect. . . . .	504		
# 22-322 PRS. . . . .	Uptown. . . . .	505		
# 22-322 PTK. . . . .	Vantage. . . . .	506		
# 22-325 COB. . . . .	Vantage Highback. . . . .	506		
# 22-325 PAC. . . . .	Vantage Point/Surveyor. . . . .	506		
# 22-325xxxGB1B. . . . .	<b>Snug Seat</b>			
# 22-380 LGA. . . . .	# 200-1000. . . . .	507		
# 22-380 MSA. . . . .	# 600-1000. . . . .	508		
# 22-627 WAV. . . . .	# E9L32. . . . .	509		
# 22077x. . . . .	Gorilla. . . . .	507		
# 22078x. . . . .	Spelcast. . . . .	508		
# 22151. . . . .	Traveller Plus. . . . .	509		
# 22152x. . . . .	<b>Strolee</b>			
# 22159x. . . . .	# 599. . . . .	511		
# 22172x. . . . .	# 605. . . . .	513		
# 22177x. . . . .	# 609. . . . .	512		
# 22178x. . . . .	# 610. . . . .	512		
# 22185x. . . . .	GT 3000. . . . .	514		
# 22188x. . . . .	Quick Click. . . . .	513		
# 22195x. . . . .	Wee Care. . . . .	510, 511, 512		
# 22356x. . . . .	<b>Team-Tex</b>			
# 22412x. . . . .	# 374099. . . . .	515		
# 22449. . . . .	# 374199. . . . .	516		
# 22450. . . . .	Babyride. . . . .	515, 516		
# 22451. . . . .	<b>Triple Play (see Safeline Kids also)</b>			
# 22452. . . . .				

Car Seat Recalls and Safety Notifications: MODELS 10 YEARS OLD AND OLDER