



# Current Model List

730 Martin Luther King Jr Blvd Suite 300 Campus Box 3430 Chapel Hill, NC 27599-3430 | [www.hsrb.unc.edu](http://www.hsrb.unc.edu)

## HIGHWAY SAFETY RESEARCH CENTER CURRENT CAR SEAT RECALL LIST

Last Revision: April 24, 2025

Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)

### About Car Seats and Recalls

It is important for people to register their car seat with the manufacturer so that they are notified of recalls. Recalls can be issued for any failure to meet Federal Motor Vehicle Safety Standard (FMVSS) 213 including crashworthiness and deviations from the standards related to labeling, flammability, or for parts that may come loose and pose a choking hazard. All recalls should be corrected.

Car seats are required to have a label indicating the manufacturer, model information, and date of manufacture. If the label is missing on a car seat, contact the manufacturer to see if it can be identified through other information. A car seat should not be used if its recall status cannot be determined.

To report any suspected car seat defects, call the National Highway Traffic Safety Administration Auto Safety Hotline at 888-327-4236 / (TTY): 800-424-9153.

### About the HSRC Recall List

UNC Highway Safety Research Center compiles and updates this list based on information provided by the National Highway Traffic Safety Administration and the car seat manufacturers at the time the recall is announced. While every effort is made to keep this list up to date, sometimes new information is added or clarified after a recall is announced. Always confirm recall information with the car seat manufacturer. It is the manufacturer who can and should make the final determination if a specific car seat is subject to recall. Caregivers should contact the manufacturer's customer service with any questions.

### About Older Car Seats and Recalls

UNC HSRC also maintains an archived list of recalled car seats that are 10 or more years old. This list can be provided upon request. While these seats are likely expired in addition to being recalled, this list is provided for those circumstances where caregivers are using an expired seat and Technicians need to be able to check its recall status.

### Instructions for Using the HSRC Recall List

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the seat's information matches any listings on the recall list. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

### For further information, contact:

Bevan Kirley or Kristel Robison  
UNC Highway Safety Research Center  
[cps@hsrb.unc.edu](mailto:cps@hsrb.unc.edu)

Sign up for Recall List Updates



**About the HSRC Recall List**

The UNC Highway Safety Research Center compiles and updates this list based on information provided by the National Highway Traffic Safety Administration and the car seat manufacturers at the time the recall is announced. While every effort is made to keep this list up to date, sometimes new information is added or clarified after a recall is announced. Always confirm recall information with the car seat manufacturer. It is the manufacturer who can and should make the final determination if a specific car seat is subject to recall. Caregivers should contact the manufacturer's customer service with any questions.

**Instructions for Using the HSRC Recall List**

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the seat's information matches any listings on the recall list. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

**Refer to Page 8 for the Index of Recalls and Safety Notifications**

**Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](https://buckleupnc.org/car-seat-recall-list)**

<b>List No.</b>	<b>Model Name</b>	<b>Model No. (X or # = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>4moms</b>				
1)	Infant Car Seat	1032	07/01/16-10/31/16	The hooks that lock the carrier into the base can stick and fail to attach the carrier to the car seat base. Contact mfg. for free replacement seat.
<b>Angel Guard (Merritt Manufacturing)</b>				
2)	AngelRide Car Bed	All Models	08/08/19-10/24/19	The internal harness may not have been properly sewn where the buckle is attached. Contact mfg. for free replacement harness.
<b>babidéal (Dorel China America)</b>				
3)	Storm Booster	BC901BPXL	02/28/19	The label attached to the fabric cover may not have the required safety warnings and instructions. Affected models do not comply with FMVSS 213 labeling requirements. Contact mfg. for free replacement fabric cover.
<b>Baby Jogger</b>				
4)	City GO Infant Car Seat	BJ64510, BJ64529	11/03/14-04/30/15	The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
<b>Baby Trend</b>				
5)	Hybrid 3-in-1 LX	FB48417, FB58181	07/14/16 - 07/23/16	The center adjuster may detach in a crash when used in the harnessed mode with a child weighing more than 40lbs. Contact mfg. for free replacement seat.
6)	Hybrid 3-in-1 Combination Booster Car Seats	FB49E14A	12/06/21	The LATCH webbing that secures the child restraint system to the lower anchorages may fray, which can reduce the strength of the webbing and fail to properly restrain a child in a crash. Contact manufacturer for replacement LATCH assembly webbing and installation instructions. Owners can continue to safely use the car seat by installing with the vehicle seat belt as outlined in the product instruction manual.

List No.	Model Name	Model No. (X or # = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
<b>Britax</b>			<b>888-427-4829 / 704-409-1699 - <a href="mailto:Britax.Recall@britax.com">Britax.Recall@britax.com</a> / <a href="http://www.britaxusa.com">www.britaxusa.com</a></b>	
7)	B-Safe 35 B-Safe 35 Travel Systems	E1A183F, E1A185x, E1A186R, E1A203F, E1A205x, E1A206x, E1A207E, E9LU65V, E9LU66x, E9LU67x, EXA185M, S02063xxx, S03803xxx, S04144xxx, S04145000, S04402800, S04884xxx, S04975600, S04978900, S05260200, S06020xxx, S06147100, S921800	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
8)	B-Safe 35 Elite B-Safe 35 Elite Travel Systems	E1A215x, E1A216P, E1A221Q, E1A225x, E1A226L, E9LS5xx, EXA216L, S01298600, S02063xxx, S02064000, S04281xxx, S04628500, S06018800, S06020xxx, S06051300, S923700	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
9)	B-Safe BOB 35	E9LT34x, E9LT35X, EXLT34A	11/01/15- 05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
10)	Companion	E9L14, E9L20, E9L80	All	Consumer Advisory - NOT A RECALL: Britax advises that the user should adjust the carrier handle so that it is completely down and behind the carrier after installation in the vehicle with or without the base assembly. Contact mfg. for additional info.
11)	One4Life Slim ClickTight	E1D197A, E1D197B, E1D197F, E1D197G	7/10/24- 7/12/24	Labels and user guide state an incorrect weight limit for rear-facing installation using the lower anchors. The maximum child weight for rear-facing installation with the lower anchors should be 35lbs. Contact manufacturer for replacement labels and instructions.
<b>Chicco USA</b>			<b>877-424-4226 - <a href="http://www.chiccousa.com">www.chiccousa.com</a></b>	
>> 12)	MyFit Zip Air	07079561970070, 04079561190070	09/01/20– 08/31/24	The car seat may allow excessive chest movement in a crash when used in the harnessed mode and installed using the following configuration: lap belt only, no tether, and recline position 3 or 4 (most upright). The car seat can continue to be used when installed using a different method, in accordance with the manufacturer's instructions. Note: manufacturer instructions indicate use of a tether is required when used in harnessed mode. Contact manufacturer for more information.
<b>Clek</b>			<b>866-656-2462 - <a href="http://www.clekinc.com">www.clekinc.com</a></b>	
13)	Flo	FL15, FL16, FL17, FL18, FL19	07/05/14- 05/20/21	It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact manufacturer for a remedy kit.
14)	Foonf	F012, F014, F015, F016, F017, F018, F019	12/03/12- 05/20/21	It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact manufacturer for a remedy kit.
15)	Liing	LG19U1	03/27/19- 09/14/20	A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact manufacturer for a remedy kit.

<b>List No.</b>	<b>Model Name</b>	<b>Model No. (X or # = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Clek (continued)</b>				
16)	Liing	LG19U1	03/27/19-02/22/21	The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact manufacturer for a remedy kit.
17)	Liingo	LGO20U1	05/20/20-04/14/20	A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact manufacturer for a remedy kit.
18)	Liingo	LGO20U1	05/20/20-02/22/21	The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact manufacturer for a remedy kit.
19)	Olli	NA	01/20/20-05/10/22	Seat does not include a model number on label. All seats manufactured within the date range are included. A required label showing the proper way to install the booster seat with a lap/shoulder belt is missing. Contact manufacturer for a replacement label (clekinc.com/olliozzilabel).
20)	Ozzi	NA	03/01/20-05/10/22	Seat does not include a model number on label. All seats manufactured within the date range are included. A required label showing the proper way to install the booster seat with a lap/shoulder belt is missing. Contact manufacturer for a replacement label (clekinc.com/olliozzilabel).
<b>Combi USA</b>			<b>800-992-6624 / 803-548-6633 - <a href="http://www.combi-intl.com">www.combi-intl.com</a></b>	
21)	BabyRide	378099	05/01/16-08/31/19	The 1-inch-wide front webbing strap used to adjust the harness does not meet FMVSS 213 breaking strength requirements and in certain circumstances, may not adequately restrain a child during a crash. Contact mfg. for more information.
22)	Coccoro	8220x	01/01/09-06/29/16	Too much force can be placed on the child when the car seat is installed forward-facing with only the vehicle's lap belt. All other installation methods are not affected. Contact mfg. for a cover to add to the bottom of the seat.
<b>Cybex (Columbus Trading-Partners USA)</b>			<b>877-242-5676 <a href="http://cybex-online.com/en-us">cybex-online.com/en-us</a></b>	
23)	Aton	514xxxxxx	06/06/17-11/01/20	The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.
24)	Aton 2, Aton 2 SensorSafe	515xxxxxx, 519xxxxxx, 521xxxxxx	06/06/17-11/01/20	The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.
25)	Aton G	522001441, 522001443, 522001445, 522001447, 522004777, 522004779	02/20/23-05/10/24	The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.
26)	Aton G Swivel	522004167, 522004169, 522004171, 522004173, 522005099, 522004781, 522004783	02/20/23-05/10/24	The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.
27)	Aton M, Aton M SensorSafe	518xxxxx, 519xxxxxx	06/06/17-11/01/20	The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.
28)	Aton Q	515xxxxxx, 517xxxxxx	06/06/17-11/01/20	The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.
29)	Cloud Q, Cloud Q SensorSafe	515xxxxxx, 517xxxxxx, 519xxxxxx, 521xxxxxx	06/06/17-11/01/20	The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.

List No.	Model Name	Model No. (X or # = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
Cybex (CTP) (continued)				
30)	Eos and Aton G Travel System	522003793, 522003795, 522003797, 522003799, 522003897	02/20/23-05/10/24	The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.
>> 31)	Eos and Aton G Swivel Travel System	522004805, 522005355	02/20/23-05/10/24	The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.
32)	Sirona M	518000385, 518000387, 518002145, 518002149, 518002151, 518002153, 519000211	11/03/17-08/31/18	It is possible for a child to access and pick pieces of foam from the child seat headrest pad. Loose pieces of form can be a choking hazard. Contact manufacturer for a remedy kit.
Diono855-463-4666 - www.us.diono.com				
33)	Cambria 2	31200-US-01, 31201-US-01, 31202-US-01	09/05/20-11/30/20	When used as a highback booster, a crack between the headrest and backrest can occur in a crash, allowing the headrest to separate. Affected products have serial numbers that start with 648762, 648801, 648802, 648803, 648825, 648842, 648843, 648844, 648846, 648847, 648925, or 648926. Contact mfg. for a replacement backrest/headrest.
34)	Olympia	30100	04/12/14-03/31/15	The seat may not adequately protect a child in a crash when used in harnessed mode and installed forward-facing.  Children who weigh more than 65 lbs: Seats installed forward-facing (with any installation method) require the use of a top tether for children weighing more than 65 lbs in harnessed mode. If no top tether anchor is available, use the seat in booster mode.  Children who weigh 65 lbs or less: Seats installed forward-facing using only the lap belt require the use of the top tether for children who weigh 65 lbs or less in harnessed mode. If no top tether anchor is available, contact mfg. for a free repair kit.
35)	Pacifica	30400, 300000	04/12/14-05/13/16	
36)	Radian R100	16600, 16000	01/03/14-09/05/17	
37)	Radian R120	16800, 16000	01/03/14-08/30/17	
38)	Radian RXT	16900, 16000	11/25/13-09/05/17	
39)	Rainier	30300, 300000	04/12/14-09/05/17	
Disney Baby (Dorel)877-657-9546 / www.djgusa.com				
>> 40)	MagicSquad 3-in-1	BC167GNT, BC167GNU	02/28/23-03/07/25	The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.
Evenflo800-525-2472 / 800-233-5921 / 800-490-7497 - www.evenflo.com				
>> 41)	Amp	34011243C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 42)	Big Kid LX	31912381C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.

<b>List No.</b>	<b>Model Name</b>	<b>Model No. (X or # = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Problem Type and Consumer Action</b>
<b>Evenflo (continued)</b>				
>> 43)	Everyfit All4One, Everykid	CS300212376C, CS300212408C, CS300212340C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 44)	Everystage DLX	39212241C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
45)	Evolve 3-in-1	34411700, 34411741	02/26/15-02/09/16	The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.
>> 46)	Gold Revolve360	38412311C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 47)	Go Time Sport Booster	35012433C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 48)	LiteMax (incl. those sold with travel system)	6391600C, 53212311C, 56211976C, 57312205C, 53112311C, 53312418C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 49)	Maestro Sport	34912200C, 34912258C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 50)	Safemax (incl. those sold with travel system)	56012477C, 57112454C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 51)	Sonus	34712059C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 52)	Spectrum	34212036C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 53)	Symphony Elite, Symphony Sport, Symphony DLX	34611709C, 34512335C, 34612173C, 34631038C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
>> 54)	Tribute	3811198C	01/01/18-12/31/24	Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.
<b>Graco</b>				
<b>800-345-4109 - www.gracobaby.com</b>				
55)	Extend2Fit	1954477	11/27/15-01/20/16	The recline labels on affected models do not meet FMVSS 213. Labels on the side of affected car seats, including the recline label, may not be in the same language (i.e. all English on one side of the car seat and all Spanish on the other side). Recall does not affect the safety performance of the seat. Contact mfg for replacement labels.
56)	Milestone	1910130, 1923980, 1926538, 1926539	07/09/15-10/09/15	The labels on affected seats do not include specific phrasing about how to install the car seat, as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for free replacement labels.

List No.	Model Name	Model No. (X or # = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
<b>Graco (continued)</b>				
57)	TurboBooster	1963973, 1963974, 1963975, 1963976, 1967886, 1975173	12/22/15- 04/05/16	Instructions are missing the information required by FMVSS 213 that the seats should be securely belted to the vehicle at all times, even if the seat is unoccupied. Recall does not affect the safety performance of the seat. Contact mfg. to obtain missing instructions.
<b>Harmony</b>			<b>877-306-1001 / <a href="http://www.harmonyjuvenile.com">www.harmonyjuvenile.com</a></b>	
58)	Big Boost Deluxe	All Models	11/01/15- 06/24/17	In the event of a crash, a child's chest may experience forces that exceed FMVSS 213 limits. Owners should contact Harmony customer service for more information.
<b>JD E-Commerce America</b>			<b>302-426-4543 / <a href="mailto:overseas-service@jd.com">overseas-service@jd.com</a></b>	
59)	Marainbow	Any Model	Any Date	This seat (as well as materially similar products – see portable infant/child seat) does not meet FMVSS 213 requirements for installation and labeling and may increase the risk of injury. Contact manufacturer for a refund and do not use seat.  A list of specific seats included in this recall: <a href="https://static.nhtsa.gov/odi/rci/2022/RMISC-22C008-4093.pdf">https://static.nhtsa.gov/odi/rci/2022/RMISC-22C008-4093.pdf</a>
60)	<b>Joybuy Express</b>	<b>See JD E-Commerce America</b>		
<b>Maxi-Cosi (Dorel)</b>			<b>877-657-9546 / <a href="http://www.djgusa.com">www.djgusa.com</a></b>	
61)	Coral XP	IC313xxx	05/01/20- 02/28/23	<b>Recall issue #1)</b> The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base. Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat.  <b>Recall issue #2)</b> The inner carrier of the child restraint is not sufficient to restrain a child without the use of the outer carrier. Only use the inner carrier when attached to the outer carrier and installed with the vehicle seat belt (see above recall), consistent with the existing instruction booklet and labels. Contact manufacturer for refund or replacement seat. Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat.
	<i>Coral XP Travel Systems:</i>			
	Mara XT	TR434xxx		
	Tayla XP	TR433xxx		
62)	Infant Car Seat Base	IC335xxx	05/01/20- 02/28/23	The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.
63)	Mico XP Max Infant Car Seat	IC336xxx, IC337xxx, IC338xxx	05/01/20- 02/28/23	The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.  Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat.
	<i>Mico XP Travel Systems:</i>			
	Adorra	TR430xxx		
	Gia XP	TR416xxx		
	Tayla	TR428xxx		
	Zelia 2 Max	TR427xxx		
64)	Mico Luxe + Infant Car Seat	IC370xxx	05/01/20- 02/28/23	The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.

List No.	Model Name	Model No. (X or # = more numbers or letters follow)	Mfg Date	Problem Type and Consumer Action
65)	Pria 70	CC133xxx	01/01/19 - 07/31/19	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.
66)	Pria 85 Pria 85 Max	CC121xxx, CC156xxx, CC182xxx, CC183xxx, CC191xxx, CC201xxx, CC212xxx, CC213xxx, CC217xxx, CC221xxx	01/01/19-08/17/21	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.
<b>Nuna</b>		<b>855-686-2891 - <a href="http://www.nunababy.com">www.nunababy.com</a></b>		
67)	Rava	All Models	07/16/16-10/25/23	Debris may enter the front harness adjuster and cause the teeth of the adjuster mechanism to no longer properly clamp onto the adjuster strap. This can result in the harness not remaining tight. If the harness is functioning properly, the car seat can continue to be used in accordance with manufacturer instructions. Contact manufacturer for a remedy kit.
<b>Portable Child/Infant Seat</b>		<b>Contact NHTSA 888-327-4236 / <a href="https://www.nhtsa.gov/report-a-safety-problem">https://www.nhtsa.gov/report-a-safety-problem</a> with concerns.</b>		
68)	<b>Consumer Advisory</b> – A number of products sold as "portable child/infant seats" fail to meet FMVSS213 requirements for protection, installation, and/or labeling and may increase the risk of injury. These seats are not certified for the protection of children in the U.S.			
Signs of seats that fail to meet FMVSS213: no lower anchor attachments, labels in languages other than English and Spanish (or missing entirely), no manufacturer contact information, and/or missing instruction labels with pictures or diagrams.				
<b>Safety 1st (Dorel)</b>		<b>877-657-9546 / <a href="http://www.djgusa.com">www.djgusa.com</a></b>		
>> 69)	Boost & Go, Boost & Go Essential	BC163HAS, BC163HAY, BC181HFW, BC181HFW, D, BC181HGW	02/28/23-03/07/25	The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.
>> 70)	Comfort Ride 3 in 1	BC159GKO, BC159HAA, BC159HBE, BC159HBED, BC159HBH	02/28/23-03/07/25	The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.
>> 71)	Grow & Go Sprint	CC321GYU, CC321GYUD, CC321GY, CC321GYD, CC321HAO, CC321HAR	02/28/23–12/31/23	Children may be able to pick off pieces of the headrest foam, creating a choking hazard. Contact manufacturer for a free replacement headrest pad assembly kit.
72)	Onboard35 SecureTech / SecureTech Base	IC351xxx IC372xxx	05/01/20-02/28/23	The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.
73)	<b>Snuggli</b>	<b>See Evenflo</b>		
<b>WAYB</b>		<b>888-924-9292 - <a href="http://www.wayb.com">www.wayb.com</a></b>		
74)	Pico	All Models CSTPI-##-001	03/01/19-05/12/19	The headrest's aluminum tubular frame can break allowing the headrest to detach. Contact mfg. for replacement headrest and instructions.



## Index of Recalls and Safety Notifications

For the model numbers, "x" or "#" means that more numbers or letters follow.

Model numbers and model names for car seats under recall are followed by their index number which corresponds to the "List No." for each listing. If the model number is not found, check the model name also. Model numbers are not available for all model names.

<b>4moms</b>		# EXLT34A . . . . .	9	Liingo . . . . .	17, 18
# 1032 . . . . .	1	# S01298600 . . . . .	8	Olli . . . . .	19
Infant Car Seat . . . . .	1	# S02063xxx . . . . .	7, 8	Ozzi . . . . .	20
		# S02064000 . . . . .	8		
<b>Angel Guard (Merritt Manufacturing)</b>		# S03803xxx . . . . .	7	<b>Combi</b>	
AngelRide Car Bed . . . . .	2	# S04144xxx . . . . .	7	# 378099 . . . . .	21
		# S04145000 . . . . .	7	# 8220x . . . . .	22
<b>babidéal (Dorel China America)</b>		# S04281xxx . . . . .	8	BabyRide . . . . .	21
# BC901BPXL . . . . .	3	# S04402800 . . . . .	7	Coccoro . . . . .	22
Storm Booster . . . . .	3	# S04628500 . . . . .	8		
		# S04884xxx . . . . .	7		
<b>Baby Jogger</b>		# S04975600 . . . . .	7	<b>Cybex (CTP)</b>	
# BJ64510 . . . . .	4	# S04978900 . . . . .	7	# 514xxxxxx . . . . .	23
# BJ64529 . . . . .	4	# S05260200 . . . . .	7	# 515xxxxxx . . . . .	24, 28, 29
City GO Car Seat . . . . .	4	# S06018800 . . . . .	8	# 517xxxxxx . . . . .	28, 29
		# S06020xxx . . . . .	7, 8	# 518000385 . . . . .	32
<b>Baby Trend</b>		# S06051300 . . . . .	8	# 518000387 . . . . .	32
# FB48417 . . . . .	5	# S06147100 . . . . .	7	# 518002145 . . . . .	32
# FB49E14A . . . . .	6	# S921800 . . . . .	7	# 518002149 . . . . .	32
# FB58181 . . . . .	5	# S923700 . . . . .	8	# 518002151 . . . . .	32
Hybrid 3-in-1 Combo Booster Seat . . . . .	6	B-Safe 35 . . . . .	7	# 518002153 . . . . .	32
Hybrid 3-in-1 LX . . . . .	5	B-Safe 35 Elite . . . . .	8	# 518xxxxxx . . . . .	27
		B-Safe 35 Elite Travel Systems . . . . .	8	# 519000211 . . . . .	32
<b>Britax</b>		B-Safe 35 Travel Systems . . . . .	7	# 519xxxxxx . . . . .	24, 27, 29
# E1A183F . . . . .	7	B-Safe BOB 35 . . . . .	9	# 521xxxxxx . . . . .	24, 29
# E1A185x . . . . .	7	Companion . . . . .	10	# 522001441 . . . . .	25
# E1A186R . . . . .	7	One4Life Slim ClickTight . . . . .	11	# 522001443 . . . . .	25
# E1A203F . . . . .	7			# 522001445 . . . . .	25
# E1A205x . . . . .	7	<b>Chicco</b>		# 522001447 . . . . .	25
# E1A206x . . . . .	7	# 04079561190070 . . . . .	12	# 522003793 . . . . .	30
# E1A207E . . . . .	7	# 07079561970070 . . . . .	12	# 522003795 . . . . .	30
# E1A215x . . . . .	8	MyFit Zip Air . . . . .	12	# 522003797 . . . . .	30
# E1A216P . . . . .	8			# 522003799 . . . . .	30
# E1A221Q . . . . .	8	<b>Clek</b>		# 522003897 . . . . .	30
# E1A225x . . . . .	8	# F012 . . . . .	14	# 522004167 . . . . .	26
# E1A226L . . . . .	8	# F014 . . . . .	14	# 522004169 . . . . .	26
# E1D197A . . . . .	11	# F015 . . . . .	14	# 522004171 . . . . .	26
# E1D197B . . . . .	11	# F016 . . . . .	14	# 522004173 . . . . .	26
# E1D197F . . . . .	11	# F017 . . . . .	14	# 522004777 . . . . .	25
# E1D197G . . . . .	11	# F018 . . . . .	14	# 522004779 . . . . .	25
# E9L14 . . . . .	10	# F019 . . . . .	14	# 522004781 . . . . .	26
# E9L20 . . . . .	10	# FL15 . . . . .	13	# 522004783 . . . . .	26
# E9L80 . . . . .	10	# FL16 . . . . .	13	# 522004805 . . . . .	31
# E9LS5xx . . . . .	8	# FL17 . . . . .	13	# 522005099 . . . . .	26
# E9LT34x . . . . .	9	# FL18 . . . . .	13	# 522005355 . . . . .	31
# E9LT35X . . . . .	9	# FL19 . . . . .	13	Aton . . . . .	23
# E9LU65V . . . . .	7	# LG19U1 . . . . .	15, 16	Aton 2 . . . . .	24
# E9LU66x . . . . .	7	# LGO20U1 . . . . .	17, 18	Aton 2 SensorSafe . . . . .	24
# E9LU67x . . . . .	7	Flo . . . . .	13	Aton G . . . . .	25
# EXA185M . . . . .	7	Foonf . . . . .	14	Aton G Swivel . . . . .	26
# EXA216L . . . . .	8	Liing . . . . .	15, 16	Aton M . . . . .	27
				Aton M SensorSafe . . . . .	27

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Cybex (CTP) (continued)**

Aton Q	28
Cloud Q	29
Cloud Q SensorSafe	29
Eos and Aton G Swivel Travel System	31
Eos and Aton G Travel System	30
Sirona M	32

**Diono**

# 16000	36, 37, 38
# 16600	36
# 16800	37
# 16900	38
# 300000	35, 39
# 30100	34
# 30300	39
# 30400	35
# 31200-US-01	33
# 31201-US-01	33
# 31202-US-01	33
Cambria 2	33
Olympia	34
Pacifica	35
Radian R100	36
Radian R120	37
Radian RXT	38
Rainier	39

**Disney Baby (Dorel)**

# BC167GNT	40
# BC167GNU	40
MagicSquad 3-in-1	40

**Dorel (Disney Baby)**

# BC167GNT	40
# BC167GNU	40
MagicSquad 3-in-1	40

**Dorel (Maxi-Cosi)**

# CC121xxx	66
# CC133xxx	65
# CC156xxx	66
# CC182xxx	66
# CC183xxx	66
# CC191xxx	66
# CC201xxx	66
# CC212xxx	66
# CC213xxx	66
# CC217xxx	66
# CC221xxx	66
# IC313xxx	61
# IC335xxx	62
# IC336xxx	63
# IC337xxx	63
# IC338xxx	63
# IC370xxx	64
# TR416xxx	63
# TR427xxx	63
# TR428xxx	63

# TR430xxx	63
# TR433xxx	61
# TR434xxx	61
Adorra	63
Coral XP	61
Gia XP	63
IC335xxx	62
Mara XT	61
Mico Luxe +	64
Mico XP Max	63
Pria 70	65
Pria 85	66
Pria 85 Max	66
Tayla	63
Tayla XT	61
Zelia 2 Max	63

**Dorel (Safety 1st)**

# BC159GKO	70
# BC159HAA	70
# BC159HBE	70
# BC159HBED	70
# BC159HBH	70
# BC163HAS	69
# BC163HAY	69
# BC181HFW	69
# BC181HFW	69
# BC181HFW	69
# BC181HFW	69
# CC321GYU	71
# CC321GYUD	71
# CC321GYU	71
# CC321GYUD	71
# CC321HAO	71
# CC321HAR	71
# IC351xxx	72
# IC372xxx	72
Boost & Go	69
Boost & Go Essential	69
Comfort Ride 3 in 1	70
Grow & Go Sprint	71
Onboard35 SecureTech	72
SecureTech Base	72

**Dorel China America (babidéal)**

# BC901BPXL	3
Storm Booster	3

**Evenflo**

# 31912381C	42
# 34011243C	41
# 34212036C	52
# 34411700	45
# 34411741	45
# 34512335C	53
# 34611709C	53
# 34612173C	53
# 34631038C	53
# 34712059C	51
# 34912200C	49

# 34912258C	49
# 35012433C	47
# 3811198C	54
# 38412311C	46
# 39212241C	44
# 53112311C	48
# 53212311C	48
# 53312418C	48
# 56012477C	50
# 56211976C	48
# 57112454C	50
# 57312205C	48
# 6391600C	48
# CS300212340C	43
# CS300212376C	43
# CS300212408C	43
Amp	41
Big Kid LX	42
Everyfit All4One	43
Everykid	43
Everystage DLX	44
Evolve 3-in-1	45
Go Time Sport Booster	47
Gold Revolve360	46
LiteMax	48
Maestro Sport	49
Safemax	50
Sonus	51
Spectrum	52
Symphony DLX	53
Symphony Elite	53
Symphony Sport	53
Tribute	54

**Graco**

# 1910130	56
# 1923980	56
# 1926538	56
# 1926539	56
# 1954477	55
# 1963973	57
# 1963974	57
# 1963975	57
# 1963976	57
# 1967886	57
# 1975173	57
Extend2Fit	55
Milestone	56
TurboBooster	57

**Harmony**

# 9999 - All Models	58
Big Boost Deluxe	58

**JD E-Commerce America**

Marainbow	59
-----------	----

**Joybuy Express**

See JD E-Commerce America	60
---------------------------	----

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Maxi-Cosi (Dorel)**

# CC121xxx	66
# CC133xxx	65
# CC156xxx	66
# CC182xxx	66
# CC183xxx	66
# CC191xxx	66
# CC201xxx	66
# CC212xxx	66
# CC213xxx	66
# CC217xxx	66
# CC221xxx	66
# IC313xxx	61
# IC335xxx	62
# IC336xxx	63
# IC337xxx	63
# IC338xxx	63
# IC370xxx	64
# TR416xxx	63
# TR427xxx	63
# TR428xxx	63
# TR430xxx	63
# TR433xxx	61
# TR434xxx	61
Adorra	63
Coral XP	61
Gia XP	63
Infant Car Seat Base	62
Mara XT	61
Mico Luxe +	64
Mico XP Max	63
Pria 70	65
Pria 85	66
Pria 85 Max	66
Tayla	63
Tayla XP	61
Zelia 2 Max	63

**Merritt Manufacturing (Angel Guard)**

AngelRide Car Bed	2
-------------------	---

**Nuna**

Rava	67
------	----

**Portable Child/Infant Seat**

Any Model / Any Date	68
----------------------	----

**Safety 1st (Dorel)**

# BC159GKO	70
# BC159HAA	70
# BC159HBE	70
# BC159HBED	70
# BC159HBH	70
# BC163HAS	69
# BC163HAY	69
# BC181HFW	69
# BC181HFW D	69
# BC181HGW	69
# CC321GYU	71
# CC321GYUD	71
# CC321GY Y	71
# CC321GY YD	71
# CC321HAO	71
# CC321HAR	71
# IC351xxx	72
# IC372xxx	72
Boost & Go	69
Boost & Go Essential	69
Comfort Ride 3 in 1	70
Grow & Go Sprint	71
Onboard35 SecureTech	72
SecureTech Base	72

**WAYB**

# CSTPI-##-001	74
Pico	74