

## HIGHWAY SAFETY RESEARCH CENTER CURRENT CAR SEAT RECALL LIST

**Last Revision: September 30, 2021**

**Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)**

### **About Car Seats and Recalls**

It is very important to pay attention to recall notices and for parents to check if their seats are safe to use. Recalls can be issued for any failure to meet Federal Motor Vehicle Safety Standard 213. Most recalls are issued due to reasons related to the crashworthiness of the car seat, but some recalls are for deviations from the standards related to labeling requirements, flammability of the upholstery or padding, or for parts that may come loose and pose a choking hazard. All recalls should be corrected.

Car seats are required to have a label indicating the manufacturer, model information, and date of manufacture. Car seats should not be used if these labels are missing. It is important for people to register their car seat by either mailing the registration card to the manufacturer or by contacting the manufacturer directly.

In cases where the manufacturer of a recalled seat has gone out of business or discontinued replacement programs, parents are advised to discontinue use of the seat. Discarded seats should be taken apart and stripped of upholstery, padding and straps and then destroyed by having them crushed to prevent others from using them.

To report any suspected car seat defects, call the National Highway Traffic Safety Administration Auto Safety Hotline at 888-327-4236 / (TTY): 800-424-9153.

### **About Older Car Seats and Recalls**

The older model list includes recalled seats that are now 10 or more years old. Caregivers will sometimes choose to use older car seats even though it not recommended. Knowing that a particular model is under recall should help to encourage the caregiver to destroy the older seat and obtain a new one.

### **About the HSRC Recall List**

The UNC Highway Safety Research Center (HSRC) car seat recall list is updated as soon as possible after recall notifications are announced and after the information can be verified for completeness and accuracy. Users of this (or any other) recall list should remind parents/caregivers to contact the manufacturer to be certain whether or not a particular car seat is affected by any recalls and how to proceed with repairs or replacement.

### **Instructions for Using the HSRC Recall List**

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the manufacturer, model, and dates of manufacture match any of the listings. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

For further information, contact:

Bevan Kirley or Kristel Robison

The University of North Carolina Highway Safety Research Center

800-672-4527 x2 or [cps@hsrc.unc.edu](mailto:cps@hsrc.unc.edu)

[www.buckleupnc.org/car-seat-recall-list](http://www.buckleupnc.org/car-seat-recall-list)

This Page Intentionally Left Blank

The following lists identify recalls and safety notifications for car seats known by the UNC Highway Safety Research Center (HSRC) as of September 30, 2021. This list is updated by HSRC as soon as possible after recall notifications are announced. The most recent additions to the list are denoted by >>. Updated versions are available on-line at [www.buckleupnc.org/car-seat-recall-list](http://www.buckleupnc.org/car-seat-recall-list)

Car seats are required to have labels indicating the manufacturer, model name and number, and date of manufacture. Model names and numbers are listed for most of the recalls. For the model numbers, "x" means that more numbers or letters follow. If the label is missing on a car seat, contact the manufacturer to see if it can be identified through other information. **A car seat should not be used if its recall status cannot be determined because the model name, model number, date of manufacture or manufacturer is not available.**

Car seats manufactured before 1981 were not required to be crash tested and must not be used. Car seats beyond their expiration dates should also not be used. Most car seats expire after 6 years from the date of manufacture, but expiration dates vary by manufacturer and model. Most manufacturers stamp their car seats, on a label or in the shell, with an expiration date, typically six to eight years from the date of manufacture. If needed, you can call the manufacturer. **Models older than ten years and under recall are included on a separate list with a separate index** for use as a reference. The index for older models can be found following the last page of the "Models Less Than 10 Years Old" list and the list of older models with recalls follows the second index. **The "Models At Least 10 Years Old" list was last revised April 5, 2021.**

Some of the recalls/notifications for car seats on this list may be more or less date- or lot-specific than what is listed. More detailed information should be obtained through the manufacturer and **it is the manufacturer who can and should make the final determination if a specific car seat is subject to recall.**

Some of the recall notices are related to problems that do not make the seats unsafe in a crash, but **all problems should be corrected.** Phone numbers are provided when a corrective action can be taken. The manufacturer should advise you whether to continue using your current car seat or to obtain another one until the problem can be corrected.

**In cases where the manufacturer has gone out of business or discontinued replacement programs, you are advised to destroy the car seat and obtain and use another one as soon as possible.** Do not throw unsafe models in the trash where they can be picked up and used by others. Discarded car seats should be destroyed by having them crushed. At the very least, they should be taken apart and stripped of upholstery, padding and straps to prevent others from using them.

To report any suspected car seat or vehicle safety defects, contact the National Highway Traffic Safety Administration Auto Safety Hotline: (888) 327-4236 / (TTY): 800-424-9153.

## CAR SEATS LESS THAN 10 YEARS OLD

Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)

Refer to Page 13 for the Index of Recalls and Safety Notifications

List No.	Manufacturer	Model No. (X = more numbers or letters follow)	Customer Assistance	
	Model Name		Mfg Date	Problem Type and Consumer Action
	<b>4moms</b>		<b>4moms - 888-614-6667 / <a href="http://www.4moms.com">www.4moms.com</a></b>	
1)	Infant Car Seat	1032	07/01/16- 10/31/16	The hooks that lock the carrier into the base can stick and fail to attach the carrier to the car seat base. Contact mfg. for free replacement seat.
2)	<b>Alcot (Childcare)</b>		REFER TO OLDER MODELS LIST	
3)	<b>All Our Kids</b>		REFER TO OLDER MODELS LIST	
4)	<b>Alpha Elite (Dorel)</b>		REFER TO OLDER MODELS LIST	
5)	<b>Alpha Sport (Dorel)</b>		REFER TO OLDER MODELS LIST	

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Customer Assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
-----------------	--------------------------------	-------------------------------------------------------	-------------------------------------	-----------------------------------------

6) **American Motors**

REFER TO OLDER MODELS LIST

**Angel Guard (Merritt Manufacturing)** 317-409-0146 - [www.merrittcarseat.com](http://www.merrittcarseat.com)

- 7) AngelRide Car Bed All Models 08/08/19-10/24/19 The internal harness may not have been properly sewn where the buckle is attached. Contact mfg. for free replacement harness.

**babidéal (Dorel China America)** 877-657-9546 - [www.babideal-us.com](http://www.babideal-us.com)

- 8) Storm Booster BC901BPXL 02/28/19 The label attached to the fabric cover may not have the required safety warnings and instructions. Affected models do not comply with FMVSS 213 labeling requirements. Contact mfg. for free replacement fabric cover.

**Baby Jogger** 800-241-1848 - [www.babyjogger.com](http://www.babyjogger.com)

- 9) City GO Infant Car Seat BJ64510, BJ64529 11/03/14-04/30/15 The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
- 10) City GO Infant Car Seat Base BJ80400, BJ61500 11/03/14-04/30/15 The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
- 11) City Mini Infant Car Seat/ Stroller System BJ72510 11/03/14-04/30/15 The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.
- 12) Vue Lite Infant Car Seat/ Stroller System BJ70411, BJ70424, BJ70431 11/03/14-04/30/15 The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.

**Baby Trend** 800-328-7363 - [www.babytrend.com](http://www.babytrend.com)

- 13) Hybrid 3-in-1 LX FB48417, FB58181 07/14/16 - 07/23/16 The center adjuster may detach in a crash when used in the harnessed mode with a child weighing more than 40lbs. Contact mfg. for free replacement seat.
- 14) TrendZ Fastback 3-in-1 FB60070, FB60408 10/01/11-07/31/13 The harness buckle may become stuck in a latched condition so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.

15) **Babyhood Industries**

REFER TO OLDER MODELS LIST

16) **Basic Comfort**

REFER TO OLDER MODELS LIST

17) **Beatrix Potter (Dorel)**

REFER TO OLDER MODELS LIST

18) **Bertini (Dorel)**

REFER TO OLDER MODELS LIST

19) **Bolform Corp.**

REFER TO OLDER MODELS LIST

**Britax** 888-427-4829 / 704-409-1699 - [Britax.Recall@britax.com](mailto:Britax.Recall@britax.com) / [www.britaxusa.com](http://www.britaxusa.com)

- 20) Advocate 70-G3 E9LG81A, E9LG83x, E9LL21A, E9LL23P, E9LL23Y 06/01/12-08/31/12 Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.

List No.	Manufacturer Model Name	Model No. (X = more numbers or letters follow)	Customer Assistance	
			Mfg Date	Problem Type and Consumer Action
<b>Britax (continued)</b>				
21)	Advocate ClickTight	E1A025Q, E9LT95N, E9LT95Q, E9LT95Z	08/01/14-07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.
22)	B-Safe 35 B-Safe 35 XE	E9LU65M, E9LU65P, E9LU63F, E9LU66R, EXLU65M, E9LS63F	10/01/14-07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit <a href="http://www.bsaf35recall.com">www.bsaf35recall.com</a> for more information.
23)	B-Safe 35 Travel System B-Agile Travel System	S914900, S915400, S915200, S01635200, S921900	10/01/14-07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit <a href="http://www.bsaf35recall.com">www.bsaf35recall.com</a> for more information.
24)	B-Safe 35 B-Safe 35 Travel Systems	E1A183F, E1A185x, E1A186R, E1A203F, E1A205x, E1A206x, E1A207E, E9LU65V, E9LU66x, E9LU67x, EXA185M, S02063xxx, S03803xxx, S04144xxx, S04145000, S04402800, S04884xxx, S04975600, S04978900, S05260200, S06020xxx, S06147100, S921800	11/01/15-05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
25)	B-Safe 35 Elite B-Safe 35 Elite XE	E9LS55T, E9LS56P, E9LS55U, E9LS66C, E9LS65U	10/01/14-07/01/15	Cracks may develop in the carry handle, potentially resulting in injury if the cracks cause the handle to break. Recall does not affect the safety performance of the seat when used in a motor vehicle. Customers may continue using the car seat when secured in a vehicle or stroller but should not lift or carry the seat by the carry handle until the remedy kit has been installed. Contact mfg. for repair kit. Visit <a href="http://www.bsaf35recall.com">www.bsaf35recall.com</a> for more information.
26)	B-Safe 35 Elite B-Safe 35 Elite Travel Systems	E1A215x, E1A216P, E1A221Q, E1A225x, E1A226L, E9LS5xx, EXA216L, S01298600, S02063xxx, S02064000, S04281xxx, S04628500, S06018800, S06020xxx, S06051300, S923700	11/01/15-05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
27)	B-Safe BOB 35	E9LT34x, E9LT35X, EXLT34A	11/01/15-05/31/17	The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.
28)	Boulevard 70- G3	E9LJ91x, E9LJ92E, E9LJ93P, E9LJ93S, E9LK91A	06/01/12-08/31/12	Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Customer Assistance Problem Type and Consumer Action</b>
<b>Britax (continued)</b>				
29)	Boulevard ClickTight	E1A015Q, E1A016A, E1A016H, E1A135Q, E9LT85Q, E9LT85S, E9LT86A, E9LT86F, E9LT86G, E9LT86H	08/01/14-07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.
30)	Companion	E9L14, E9L20, E9L80	All	Consumer Advisory - NOT A RECALL: Britax advises that the user should adjust the carrier handle so that it is completely down and behind the carrier after installation in the vehicle with or without the base assembly. Contact mfg. for additional info.
31)	Marathon ClickTight	E1A005R, E1A006B, E1A116L, E9LT71Q, E9LT75R, E9LT76B, E9LT76L, E9LT76N, E9LT76P, EXA116L	08/01/14-07/29/15	The harness adjuster button (red) on affected models may remain down in the "release" position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child's movements while secured in the seat. Contact mfg. for repair kit.
32)	Pavilion 70-G3	E9LK31x, E9LK32x, E9LK33Q, E9LL11x, E9LL12x	06/01/12-08/31/12	Children who bite or chew on the shoulder strap HUGS pads could bite off small pieces, presenting a choking hazard. Contact mfg. for replacement HUGS pads and instructions.
33)	<b>Century Products</b>			<b>REFER TO OLDER MODELS LIST</b>
34)	<b>Chicco</b>			<b>REFER TO OLDER MODELS LIST</b>
35)	<b>Chrysler</b>			<b>REFER TO OLDER MODELS LIST</b>
36)	<b>Collier-Keyworth</b>			<b>REFER TO OLDER MODELS LIST</b>
<b>Combi USA</b>				<b>800-992-6624 / 803-548-6633 - www.combi-intl.com</b>
>> 37)	BabyRide	378099	05/01/16-08/31/19	The 1-inch-wide front webbing strap used to adjust the harness does not meet FMVSS 213 breaking strength requirements and in certain circumstances, may not adequately restrain a child during a crash. Contact mfg. for more information.
38)	Coccoro	8220	01/06/09 - 12/05/12	Harness webbing fails to meet FMVSS 213 minimum breaking strength requirements. Contact mfg. for free harness replacement kit and instructions. The seats can continue to be used until the kits are made available and repairs are made.
39)	Coccoro	8220x	01/01/09-06/29/16	Too much force can be placed on the child when the car seat is installed forward-facing with only the vehicle's lap belt. All other installation methods are not affected. Contact mfg. for a cover to add to the bottom of the seat.
40)	Zeus 360	8836	02/25/09 - 05/24/12	Harness webbing fails to meet FMVSS 213 minimum breaking strength requirements. Contact mfg. for free harness replacement kit and instructions. The seats can continue to be used until the kits are made available and repairs are made.
41)	<b>Compass Baby</b>			<b>REFER TO OLDER MODELS LIST</b>
<b>Cosco (Dorel)</b>				<b>Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 www.djgusa.com</b>
42)	Comfy Carry	IC123 FSM	05/01/11-04/25/12	Some models were sold without a base and therefore did not provide lower LATCH attachments as required by FMVSS 213. Carriers can safely be installed without the base using the seat belt. Contact mfg. to obtain a base.

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Mfg Date</b>	<b>Customer Assistance Problem Type and Consumer Action</b>
<b>Diono</b>			<b>855-463-4666 - www.us.diono.com</b>	
43)	Cambria 2	31200-US-01, 31201-US-01, 31202-US-01	09/05/20- 11/30/20	When used as a highback booster, a crack between the headrest and backrest can occur in a crash, allowing the headrest to separate. Affected products have serial numbers that start with 648762, 648801, 648802, 648803, 648825, 648842, 648843, 648844, 648846, 648847, 648925, or 648926. Contact mfg. for a replacement backrest/headrest.
44)	Olympia	30100	04/12/14- 03/31/15	The seat may not adequately protect a child in a crash when used in harnessed mode and installed forward-facing.
45)	Pacifica	30400, 300000	04/12/14- 05/13/16	<b>Children who weigh more than 65 lbs:</b> Seats installed forward-facing (with any installation method) require the use of a top tether for children weighing more than 65 lbs in harnessed mode. If no top tether anchor is available, use the seat in booster mode.
46)	Radian R100	16600, 16000	01/03/14- 09/05/17	
47)	Radian R120	16800, 16000	01/03/14- 08/30/17	<b>Children who weigh 65 lbs or less:</b> Seats installed forward-facing using only the lap belt require the use of the top tether for children who weigh 65 lbs or less in harnessed mode. If no top tether anchor is available, contact mfg. for a free repair kit.
48)	Radian RXT	16900, 16000	11/25/13- 09/05/17	
49)	Rainier	30300, 300000	04/12/14- 09/05/17	
50)	<b>Disney (Dorel)</b>			<b>REFER TO OLDER MODELS LIST</b>
51)	<b>Downunder</b>			<b>REFER TO OLDER MODELS LIST</b>
52)	<b>Eddie Bauer (Dorel)</b>			<b>REFER TO OLDER MODELS LIST</b>
<b>Evenflo</b>			<b>800-525-2472 / 800-233-5921 / 800-490-7497 - www.evenflo.com</b>	
53)	Big Kid Booster	30911173AD, 3091967AD, 30911118AD, 30911120D	ALL	The affected seats - originally intended for display models - were packaged without the instruction manual or the required registration card. Otherwise, including crashworthiness, they were fully compliant with FMVSS 213. However, some seats were inadvertently shipped to institutional customers to be given to families. None of the affected units were sold at retail stores. Affected seats end with the letter "D" and have a label stating: "DISPLAY ONLY – NOT INTENDED FOR SALE," located on the back of the booster seat headrest. Contact mfg. for remedy kit.
54)	Chase Factory Select Chase LX Chase Select	306xxx	06/12/12- 10/03/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
55)	Chase DLX Chase LX	329xxx	08/23/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
56)	Embrace 35	3151198, 3151953, 31511xxx, 31521138, 46811xxx, 48111xxx, 48411xxx, 52911307A, 55311xxx, 52921040	12/01/11- 05/31/13*	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. *NOTE: Not all Embrace 35 models in the 12/01/11-05/31/13 date range are impacted. Contact mfg. for specific dates and replacement buckle if needed.

List No.	Manufacturer Model Name	Model No. (X = more numbers or letters follow)	Customer Assistance	
			Mfg Date	Problem Type and Consumer Action
<b>Evenflo (continued)</b>				
57)	Evolve 3-in-1	34411700, 34411741	02/26/15- 02/09/16	The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.
58)	Express Factory Select	329xxx	08/23/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
59)	Maestro Maestro Factory Select	310xxx	08/22/11- 10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
60)	Momentum 65 Momentum 65 DLX	385xxx	03/04/13- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
61)	Secure Kid 100 Secure Kid 300 Secure Kid 400 Secure Kid LX Secure Kid LX Factory Select	308xxx	12/13/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
62)	Snugli All-in- One	346xxx	10/02/12- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
63)	Snugli Booster	308xxx	12/13/11- 03/03/14	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
64)	Snugli Embrace 35	30711365	06/01/12- 11/30/12	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for a free repair kit.
65)	SureRide DLX	371xxx	06/20/12- 10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
66)	Symphony 65 DLX Symphony DLX Symphony LX	345xxx	10/02/12- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.



<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Customer Assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
-----------------	--------------------------------	-------------------------------------------------------	-------------------------------------	-----------------------------------------

**Evenflo (continued)**

67)	Symphony Symphony 65 E3	346xxx	10/02/12- 08/26/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
68)	Titan 65 Titan 65 Factory Select	371xxx	06/20/12- 10/17/13	The harness buckle may become resistant to unlatching over time so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. NOTE: Date ranges for specific model numbers of affected models may differ from date range listed here. Contact mfg. for specific dates and replacement buckle if needed.
69)	Transitions 3-in-1	34411029, 34411686, 34411695	12/18/14- 01/29/16	The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.

70) **Fisher Price** REFER TO OLDER MODELS LIST

71) **Ford** REFER TO OLDER MODELS LIST

72) **General Motors** REFER TO OLDER MODELS LIST

73) **Gerry** REFER TO OLDER MODELS LIST

**Graco****800-345-4109 - www.gracobaby.com**

74)	Aprica A30	All Models	07/01/11- 04/30/12	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
75)	Argos 70 / Argos 70 Elite	All Models	05/01/11- 07/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
76)	Classic Ride	1812930	03/01/14- 02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
77)	Classic Ride 50	All Models	10/01/11- 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
78)	ComfortSport	All Models	10/01/10- 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
79)	ComfortSport	1794333, 1813040	03/01/14- 02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
80)	Extend2Fit	1954477	11/27/15- 01/20/16	The recline labels on affected models do not meet FMVSS 213. Labels on the side of affected car seats, including the recline label, may not be in the same language (i.e. all English on one side of the car seat and all Spanish on the other side). Recall does not affect the safety performance of the seat. Contact mfg for replacement labels.

List No.	Manufacturer Model Name	Model No. (X = more numbers or letters follow)	Customer Assistance	
			Mfg Date	Problem Type and Consumer Action
<b>Graco (continued)</b>				
81)	Head Wise 70 with Safety Surround	All Models	01/01/12-07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
82)	Milestone	1910130, 1923980, 1926538, 1926539	07/09/15-10/09/15	The labels on affected seats do not include specific phrasing about how to install the car seat, as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for free replacement labels.
83)	My Ride 65 / My Ride 65 with Safety Surround	All Models	04/01/09-07/31/13 & 09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
84)	My Ride 65	1794334, 1813015, 1813074, 1853478, 1871689, 1872691, 1877535, 1908152	05/16/14 - 08/01/14	The harness webbing used on certain My Ride 65 convertible car seats do not meet FMVSS 213 requirements for breaking strength. Harnesses with the webbing tag code "2014/06" are the only models affected by this recall. Contact mfg. for replacement harness. Consumers may continue to use the My Ride 65 convertible car seats while waiting for a replacement kit.
85)	My Ride 70	All Models	05/01/12-07/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
86)	My Size 70	All Models	01/01/12-07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
87)	Nautilus 3-in-1 / Nautilus Elite / Nautilus Plus	All Models	10/01/07-07/31/13 & 08/19/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
88)	Ready Ride	All Models	10/01/10-09/30/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
89)	Ready Ride	1924519, 1924520	03/01/14-02/28/15	The labels of affected models did not include information about the location and use of the instruction manual as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for replacement labels.
90)	Size4Me70	All Models	01/01/12-07/31/13 & 08/03/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
91)	Smart Seat / Smart Seat with Safety Surround	All Models	12/01/10-09/30/13 & 10/09/13; 12/25/13; 1/10/14	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
92)	SnugRide, SnugRide Classic Connect	All Models	03/01/11-05/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Customer Assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
-----------------	--------------------------------	-------------------------------------------------------	-------------------------------------	-----------------------------------------

**Graco (continued)**

93)	SnugRide 30 SnugRide Classic Connect 30	All Models	07/01/10- 01/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
94)	SnugRide 35 SnugRide Classic Connect 35	All Models	05/01/11- 01/31/13	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
95)	SnugRide Click Connect 40	All Models	06/01/12- 12/31/12	The harness buckle may become stuck so that it cannot be opened by pushing the release button, thus making it difficult to remove the child from the restraint in an emergency. Contact mfg. for replacement buckle.
96)	TurboBooster	1963973, 1963974, 1963975, 1963976, 1967886, 1975173	12/22/15- 04/05/16	Instructions are missing the information required by FMVSS 213 that the seats should be securely belted to the vehicle at all times, even if the seat is unoccupied. Recall does not affect the safety performance of the seat. Contact mfg. to obtain missing instructions.

**Harmony****877-306-1001 / www.harmonyjuvenile.com**

97)	Big Boost Deluxe	All Models	11/01/15- 06/24/17	In the event of a crash, a child's chest may experience forces that exceed FMVSS 213 limits. Owners should contact Harmony customer service for more information.
-----	---------------------	------------	-----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------

98) **International**

REFER TO OLDER MODELS LIST

**Kiddy USA****855-925-4339 / info@kiddyusa.com / www.kiddyusa.com**

99)	World Plus	51 100 WP	02/01/12- 10/05/13	Recall affects all World Plus seats ever made. The buckle/tongue on the impact shield of affected seats may only partially engage, appearing to be fully latched when it is not. Kiddy will reimburse owners the full purchase price of the car seat. Contact mfg. (855-925-4339) for more information.
-----	------------	-----------	-----------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

100) **Kolcraft**

REFER TO OLDER MODELS LIST

101) **Lin Lih/MCP Ent.**

REFER TO OLDER MODELS LIST

**Maxi-Cosi (Dorel)****Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141  
www.djgusa.com**

>> 102)	Pria 70	CC133xxx	01/01/19 - 07/31/19	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.
>> 103)	Pria 85 Pria 85 Max	CC121xxx, CC156xxx, CC182xxx, CC183xxx, CC191xxx, CC201xxx, CC212xxx, CC213xxx, CC217xxx, CC221xxx	01/01/19- 08/17/21	When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.

104) **Mercedes-Benz USA**

REFER TO OLDER MODELS LIST

<b>List No.</b>	<b>Manufacturer Model Name</b>	<b>Model No. (X = more numbers or letters follow)</b>	<b>Customer Assistance Mfg Date</b>	<b>Problem Type and Consumer Action</b>
105)	<b>Mia Moda</b>			REFER TO OLDER MODELS LIST
	<b>Orbit Baby</b>		<b>877-672-2229 / 510-793-5007 - www.orbitbaby.com</b>	
106)	Car Seat Base G2	ORB822000	03/20/13-07/20/13	Voluntary recall of the Orbit Baby Car Seat Base G2 with listed manufacturer dates AND with a Batch Number of A0840, A0860, or A0880. The knob on the base used to tighten the base into the vehicle may detach or spin without tightening the base. <u>The Infant Car Seat G2 is not affected by this recall and can continue to be used without the base.</u> Contact mfg. for a free repair kit.
107)	<b>Peg Perego USA</b>			REFER TO OLDER MODELS LIST
108)	<b>Playskool</b>			REFER TO OLDER MODELS LIST
109)	<b>Pride Trimble/Virco</b>			REFER TO OLDER MODELS LIST
110)	<b>Questor</b>			REFER TO OLDER MODELS LIST
	<b>Recaro</b>		<b>888-973-2276 / 800-873-2276 / 248-364-3818/ - www.recaropromotion.com</b>	
111)	Performance RIDE	333.01.xxx	01/15/13-06/09/15	The top tether anchorage on the seat may detach from the plastic shell in a crash. Contact mfg. for repair kit.
112)	ProRIDE	332.01.xxx	04/09/10-06/09/15	The top tether anchorage on the seat may detach from the plastic shell in a crash. Contact mfg. for repair kit.
113)	ProSport	385.01.xxxx	06/16/10-01/31/13	When the affected child seats are installed with the LATCH lower anchors only (without the top tether), the child's head can move too much, increasing the risk of injury in a crash. Contact mfg. for replacement labels and complete set of new instructions informing owners to discontinue use of the LATCH system when the weight of the child reaches 40 pounds.
114)	<b>Renolux (FBS)</b>			REFER TO OLDER MODELS LIST
115)	<b>Safeline Kids (See Triple Play Products also )</b>			REFER TO OLDER MODELS LIST
	<b>Safety 1<sup>st</sup> (Dorel)</b>		<b>Dorel Juvenile Group: 866-623-3139 / 800-219-0509 / 866-611-3022 / 812-372-0141 - www.djgusa.com</b>	
116)	OnBoard 35	IC124 FSM	05/01/11-04/25/12	Some models were sold without a base and therefore did not provide lower LATCH attachments as required by FMVSS 213. Carriers can safely be installed without the base using the seat belt. Contact mfg. to obtain a base.
117)	<b>Snugli</b>			See Evenflo
118)	<b>Strolee</b>			REFER TO OLDER MODELS LIST
119)	<b>Team-TEX America</b>			REFER TO OLDER MODELS LIST
120)	<b>TriplePlay Products (See Safeline Kids also )</b>			REFER TO OLDER MODELS LIST

<i>List No.</i>	<i>Manufacturer Model Name</i>	<i>Model No. (X = more numbers or letters follow)</i>	<i>Customer Assistance</i>	
<i>No.</i>	<i>Model Name</i>		<i>Mfg Date</i>	<i>Problem Type and Consumer Action</i>

121) **TRW**

REFER TO OLDER MODELS LIST

**WAYB****WAYB: 888-924-9292 - [www.wayb.com](http://www.wayb.com)**

122) Pico

All Models  
(CSTPI-##-001)03/01/19- The headrest's aluminum tubular frame can break allowing the headrest to detach.  
05/12/19 Contact mfg. for replacement headrest and instructions.123) **XSCi**

REFER TO OLDER MODELS LIST

**Integrated (built-into the vehicle) seats**

	<b>Manufacturer</b>	<b>Model Year</b>	<b>Customer Assistance</b>
<b>Chrysler</b>			<b>800-853-1403 / 800-992-1997</b>
124)	Town and Country	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
125)	Town and Country	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
126)	Town and Country	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
127)	Town and Country	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.
<b>Dodge</b>			<b>800-853-1403 / 800-992-1997</b>
128)	Caravan Grand Caravan	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
129)	Caravan Grand Caravan	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
130)	Caravan Grand Caravan	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
131)	Caravan Grand Caravan	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.
<b>Ford</b>			<b>800-392-3673</b>
132)	Windstar	1998	The headrest lockout mechanism on the integrated child seats may not engage and lock the headrest in the "down" position, as intended. Replace bench seats with integrated child seats with seats built with revised headrest lockout mechanisms.
<b>Plymouth</b>			<b>800-853-1403 / 800-992-1997</b>
133)	Voyager Grand Voyager	1996	Bolts securing seat to frame can break. Contact Chrysler Corp. or dealer for repair
134)	Voyager Grand Voyager	1988	Harness restraint webbing incorrectly routed around the metal reinforcement bar on these seats. Child may not be properly restrained in the event of a crash. Dealers will inspect and correct improperly routed webbing.
135)	Voyager Grand Voyager	1996, 1997	Safety improvement campaign: The latch plate can remain in the locked position due to food or other items. Owners are being provided with decals/instructions describing the operation of the buckle and the latch plate
136)	Voyager Grand Voyager	1996, 1997	The harness on the integrated child seat can become difficult to release when the safety belt latch plate gets dirty. Dealers will clean the latch, modify the emergency release anchor, and provide additional instructions.

**Index of Recalls and Safety Notifications**  
For the model numbers "x" = more numbers or letters follow.

Model numbers and model names for car seats under recall are followed by their index number which corresponds to the "List No." for each listing. If the model number is not found, check the model name also. Model numbers are not available for all model names.

**Notes:**

- 1) Dorel Juvenile Group products are indexed under each individual product line (Alpha Elite, Alpha Sport, Beatrix Potter, Bertini, Cosco, Eddie Bauer, Maxi-Cosi, and Safety 1<sup>st</sup>) as well as under "Dorel."
- 2) Graco issued recalls in February and July 2014 on the harness buckles used on many convertible, harnessed booster, and infant seats manufactured from 2009 through January 2014. Since model #'s are not available for the model names included in this recall, Graco seats with dates from 2009 through January 2014 should be looked up by model name rather than number.

<b>4moms</b>		<b>Basic Comfort</b>		# E9LK91A. . . . .	28
# 1032. . . . .	1	ALL MODELS. . . . .	16	# E9LL11x. . . . .	32
Infant Car Seat. . . . .	1			# E9LL12x. . . . .	32
		<b>Beatrix Potter (Dorel)</b>		# E9LL21A. . . . .	20
<b>Alcot</b>		ALL MODELS. . . . .	17	# E9LL23P. . . . .	20
ALL MODELS. . . . .	2			# E9LL23Y. . . . .	20
<b>All Our Kids</b>		<b>Bertini (Dorel)</b>		# E9LS55T. . . . .	25
ALL MODELS. . . . .	3	ALL MODELS. . . . .	18	# E9LS55U. . . . .	25
				# E9LS56P. . . . .	25
<b>American Motors</b>		<b>Bolform</b>		# E9LS5xx. . . . .	26
ALL MODELS. . . . .	6	ALL MODELS. . . . .	19	# E9LS63F. . . . .	22
				# E9LS65U. . . . .	25
<b>Angel Guard (Merritt Manufacturing)</b>		<b>Britax</b>		# E9LS66C. . . . .	25
AngelRide Car Bed. . . . .	7	# E1A005R. . . . .	31	# E9LT34x. . . . .	27
		# E1A006B. . . . .	31	# E9LT35X. . . . .	27
<b>babidéal (Dorel China America)</b>		# E1A015Q. . . . .	29	# E9LT71Q. . . . .	31
# BC901BPXL. . . . .	8	# E1A016A. . . . .	29	# E9LT75R. . . . .	31
Storm Booster. . . . .	8	# E1A016H. . . . .	29	# E9LT76B. . . . .	31
		# E1A025Q. . . . .	21	# E9LT76L. . . . .	31
<b>Baby Jogger</b>		# E1A116L. . . . .	31	# E9LT76N. . . . .	31
# BJ61500. . . . .	10	# E1A135Q. . . . .	29	# E9LT76P. . . . .	31
# BJ64510. . . . .	9	# E1A183F. . . . .	24	# E9LT85Q. . . . .	29
# BJ64529. . . . .	9	# E1A185x. . . . .	24	# E9LT85S. . . . .	29
# BJ70411. . . . .	12	# E1A186R. . . . .	24	# E9LT86A. . . . .	29
# BJ70424. . . . .	12	# E1A203F. . . . .	24	# E9LT86F. . . . .	29
# BJ70431. . . . .	12	# E1A205x. . . . .	24	# E9LT86G. . . . .	29
# BJ72510. . . . .	11	# E1A206x. . . . .	24	# E9LT86H. . . . .	29
# BJ80400. . . . .	10	# E1A207E. . . . .	24	# E9LT95N. . . . .	21
City GO Car Seat. . . . .	9	# E1A215x. . . . .	26	# E9LT95Q. . . . .	21
City GO Car Seat Base. . . . .	10	# E1A216P. . . . .	26	# E9LT95Z. . . . .	21
City Mini Car Seat/Stroller. . . . .	11	# E1A221Q. . . . .	26	# E9LU63F. . . . .	22
Vue Lite Car Seat/Stroller. . . . .	12	# E1A225x. . . . .	26	# E9LU65P. . . . .	22
		# E1A226L. . . . .	26	# E9LU65V. . . . .	24
<b>Baby Trend</b>		# E9L14. . . . .	30	# E9LU66R. . . . .	22
# FB48417. . . . .	13	# E9L20. . . . .	30	# E9LU66x. . . . .	24
# FB58181. . . . .	13	# E9L80. . . . .	30	# E9LU67x. . . . .	24
# FB60070. . . . .	14	# E9LG81A. . . . .	20	# EXA116L. . . . .	31
# FB60408. . . . .	14	# E9LG83x. . . . .	20	# EXA185M. . . . .	24
Hybrid 3-in-1 LX. . . . .	13	# E9LJ91x. . . . .	28	# EXA216L. . . . .	26
TrendZ Fastback. . . . .	14	# E9LJ92E. . . . .	28	# EXLT34A. . . . .	27
		# E9LJ93P. . . . .	28	# EXLU65M. . . . .	22
<b>Babyhood Industries</b>		# E9LJ93S. . . . .	28	# S01298600. . . . .	26
ALL MODELS. . . . .	15	# E9LK31x. . . . .	32	# S01635200. . . . .	23
		# E9LK32x. . . . .	32	# S02063xxx. . . . .	24, 26
		# E9LK33Q. . . . .	32	# S02064000. . . . .	26

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Britax (continued)**

# S03803xxx	24
# S04144xxx	24
# S04145000	24
# S04281xxx	26
# S04402800	24
# S04628500	26
# S04884xxx	24
# S04975600	24
# S04978900	24
# S05260200	24
# S06018800	26
# S06020xxx	24, 26
# S06051300	26
# S06147100	24
# S914900	23
# S915200	23
# S915400	23
# S921800	24
# S921900	23
# S923700	26
Advocate 70-G3	20
Advocate ClickTight	21
B-Agile Travel System	23
B-Safe 35	22, 24
B-Safe 35 Elite	25, 26
B-Safe 35 Elite Travel Systems	26
B-Safe 35 Elite XE	25
B-Safe 35 Travel System	23
B-Safe 35 Travel Systems	24
B-Safe 35 XE	22
B-Safe BOB 35	27
Boulevard 70-G3	28
Boulevard ClickTight	29
Companion	30
Marathon ClickTight	31
Pavilion 70-G3	32

**Century**

ALL MODELS	33
------------	----

**Childcare**

ALL MODELS	2
------------	---

**Chrysler [Aftermarket]**

ALL MODELS	35
------------	----

**Chrysler [Integrated]**

Town and Country	124, 125, 126, 127
------------------	--------------------

**Collier-Keyworth**

ALL MODELS	36
------------	----

**Combi**

# 378099	37
# 8220	38
# 8220x	39
# 8836	40
BabyRide	37
Coccoro	38, 39
Zeus 360	40

**Compass Baby**

ALL MODELS	41
------------	----

**Cosco (Dorel)**

# IC123 FSM	42
Comfy Carry	42

**Diono**

# 16000	46, 47, 48
# 16600	46
# 16800	47
# 16900	48
# 300000	45, 49
# 30100	44
# 30300	49
# 30400	45
# 31200-US-01	43
# 31201-US-01	43
# 31202-US-01	43
Cambria 2	43
Olympia	44
Pacifica	45
Radian R100	46
Radian R120	47
Radian RXT	48
Rainier	49

**Disney (Dorel)**

ALL MODELS	50
------------	----

**Dodge [Integrated]**

Caravan	128, 129, 130, 131
Grand Caravan	128, 129, 130, 131

**Dorel (Beatrix Potter)**

ALL MODELS	17
------------	----

**Dorel (Bertini)**

ALL MODELS	18
------------	----

**Dorel (Cosco)**

# IC123 FSM	42
Comfy Carry	42

**Dorel (Disney)**

ALL MODELS	50
------------	----

**Dorel (Eddie Bauer)**

ALL MODELS	52
------------	----

**Dorel (Maxi-Cosi)**

# CC121xxx	103
# CC133xxx	102
# CC156xxx	103
# CC182xxx	103
# CC183xxx	103
# CC191xxx	103
# CC201xxx	103
# CC212xxx	103
# CC213xxx	103
# CC217xxx	103
# CC221xxx	103

Pria 70	102
Pria 85	103
Pria 85 Max	103

**Dorel (Safety 1st)**

# IC124 FSM	116
OnBoard 35	116

**Dorel China America (babidéal)**

# BC901BPXL	8
Storm Booster	8

**Downunder**

ALL MODELS	51
------------	----

**Eddie Bauer (Dorel)**

ALL MODELS	52
------------	----

**Evenflo**

# 306xxx	54
# 30711365	64
# 308xxx	61, 63
# 30911118AD	53
# 30911120D	53
# 30911173AD	53
# 3091967AD	53
# 310xxx	59
# 3151198	56
# 31511xxx	56
# 3151953	56
# 31521138	56
# 329xxx	55, 58
# 34411029	69
# 34411686	69
# 34411695	69
# 34411700	57
# 34411741	57
# 345xxx	66
# 346xxx	62, 67
# 371xxx	65, 68
# 385xxx	60
# 46811xxx	56
# 48111xxx	56
# 48411xxx	56
# 52911307A	56
# 52921040	56
# 55311xxx	56
Big Kid Booster	53
Chase DLX	55
Chase Factory Select	54
Chase LX	54, 55
Chase Select	54
Embrace 35	56
Evolve 3-in-1	57
Express Factory Select	58
Maestro	59
Maestro Factory Select	59
Momentum 65	60
Momentum 65 DLX	60
Secure Kid 100	61
Secure Kid 300	61
Secure Kid 400	61



For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

<b>Evenflo (continued)</b>	Extend2Fit..... 80	<b>Mia Moda</b>	
Secure Kid LX..... 61	Head Wise 70 + SftySurnd..... 81	ALL MODELS..... 105	
Secure Kid LX Factory Sel..... 61	Milestone..... 82	<b>Orbit Baby</b>	
Snugli All-in-One..... 62	My Ride 65..... 83, 84	# ORB822000 (Base)..... 106	
Snugli Booster..... 63	My Ride 65 + SftySurnd..... 83	Car Seat Base G2..... 106	
Snugli Embrace 35..... 64	My Ride 70..... 85	<b>Playskool</b>	
SureRide DLX..... 65	My Size 70..... 86	ALL MODELS..... 108	
Symphony..... 67	Nautilus 3-in-1..... 87	<b>Plymouth [Integrated]</b>	
Symphony 65 DLX..... 66	Nautilus Elite..... 87	Grand Voyager..... 133, 134, 135, 136	
Symphony 65 E3..... 67	Nautilus Plus..... 87	Voyager..... 133, 134, 135, 136	
Symphony DLX..... 66	Ready Ride..... 88, 89	<b>Pride Trimble/Virco</b>	
Symphony LX..... 66	Size4Me70..... 90	ALL MODELS..... 109	
Titan 65..... 68	Smart Seat..... 91	<b>Questor</b>	
Titan 65 Factory Select..... 68	Smart Seat + SftySurnd..... 91	ALL MODELS..... 110	
Transitions..... 69	Snug Ride..... 92	<b>Recaro</b>	
<b>Fisher Price</b>	Snug Ride 30..... 93	# 332.01.xxx..... 112	
ALL MODELS..... 70	Snug Ride 35..... 94	# 333.01.xxx..... 111	
<b>Ford [Aftermarket]</b>	Snug Ride Classic Conct 30..... 93	# 385.01.xxx..... 113	
ALL MODELS..... 71	Snug Ride Classic Conct 35..... 94	Performance RIDE..... 111	
<b>Ford [Integrated]</b>	Snug Ride Click Conct 40..... 95	ProRIDE..... 112	
Windstar..... 132	SnugRide Classic Connect..... 92	ProSport..... 113	
<b>General Motors [Aftermarket]</b>	TurboBooster..... 96	<b>Renolux (FBS)</b>	
ALL MODELS..... 72	<b>Harmony</b>	ALL MODELS..... 114	
<b>Gerry</b>	# 9999 - All Models..... 97	<b>Safeline Kids (see Triple Play also)</b>	
ALL MODELS..... 73	Big Boost Deluxe..... 97	ALL MODELS..... 115	
<b>Graco</b>	<b>International</b>	<b>Safety 1st (Dorel)</b>	
# 1794333..... 79	ALL MODELS..... 98	# IC124 FSM..... 116	
# 1794334..... 84	<b>Kiddy USA</b>	OnBoard 35..... 116	
# 1812930..... 76	# 51 100 WP..... 99	<b>Snugli</b>	
# 1813015..... 84	World Plus..... 99	See Evenflo..... 62, 63, 64	
# 1813040..... 79	<b>Kolcraft</b>	<b>Strolee</b>	
# 1813074..... 84	ALL MODELS..... 100	ALL MODELS..... 117, 118	
# 1853478..... 84	<b>Lin Lih/MCP</b>	<b>Team-Tex</b>	
# 1871689..... 84	ALL MODELS..... 101	ALL MODELS..... 119	
# 1872691..... 84	<b>Maxi-Cosi (Dorel)</b>	<b>TriplePlay Products</b>	
# 1877535..... 84	# CC121xxx..... 103	ALL MODELS..... 120	
# 1908152..... 84	# CC133xxx..... 102	<b>TRW</b>	
# 1910130..... 82	# CC156xxx..... 103	ALL MODELS..... 121	
# 1923980..... 82	# CC182xxx..... 103	<b>WAYB</b>	
# 1924519..... 89	# CC183xxx..... 103	# CSTPI-xx-001..... 122	
# 1924520..... 89	# CC191xxx..... 103	Pico..... 122	
# 1926538..... 82	# CC201xxx..... 103	<b>XSci</b>	
# 1926539..... 82	# CC212xxx..... 103	ALL MODELS..... 123	
# 1954477..... 80	# CC213xxx..... 103		
# 1963973..... 96	# CC217xxx..... 103		
# 1963974..... 96	# CC221xxx..... 103		
# 1963975..... 96	Pria 70..... 102		
# 1963976..... 96	Pria 85..... 103		
# 1967886..... 96	Pria 85 Max..... 103		
# 1975173..... 96	<b>Mercedes-Benz USA</b>		
Aprica A30..... 74	ALL MODELS..... 104		
Argos 70..... 75	<b>Merritt Manufacturing (Angel Guard)</b>		
Argos 70 Elite..... 75	AngelRide Car Bed..... 7		
Classic Ride..... 76			
Classic Ride 50..... 77			
ComfortSport..... 78, 79			